

**Aviation Safety Investigation Report  
199603747**

**Piper Aircraft Corp  
Seneca**

**20 October 1996**

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

**NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at [www.atsb.gov.au](http://www.atsb.gov.au).**

The Bureau did not conduct an on scene investigation of this occurrence. The information presented below was obtained from information supplied to the Bureau.

**Occurrence Number:** 199603747                      **Occurrence Type:** Accident  
**Location:** Parafield, Aerodrome  
**State:** SA    **Inv Category:** 4  
**Date:** Sunday 20 October 1996  
**Time:** 1215 hours                                      **Time Zone** CSuT  
**Highest Injury Level:** None

**Aircraft Manufacturer:** Piper Aircraft Corp  
**Aircraft Model:** PA-34-200  
**Aircraft Registration:** VH-MCK                      **Serial Number:** 34-7350145  
**Type of Operation:** Instructional Solo  
**Damage to Aircraft:** Substantial  
**Departure Point:** Parafield SA  
**Departure Time:**  
**Destination:** Parafield SA

**Crew Details:**

<u>Role</u>	<u>Class of Licence</u>	<u>Hours on Type</u>	<u>Hours Total</u>
Pilot-In-Command	Private	5.0	300

**Approved for Release:** Tuesday, November 19, 1996

The pilot was conducting solo circuit training and had completed 8 normal landings with no problems. He reported that the weather conditions were fine with no noticeable crosswind component on the runway in use.

He stated that the last approach was normal, but as he flared for landing the aircraft continued descending and touched down hard and bounced. He attempted to raise the nose to cushion the landing, but there was no response from his elevator inputs. The aircraft again contacted the ground heavily in a nose low attitude, shearing the nose landing gear attachment frame from the forward fuselage bulkhead, pushing it upwards and shattering the windscreen. Both propellers suffered ground strikes bending the blades.

The pilot may have reduced engine power too soon prior to the landing flare, resulting in a reduction of propeller slipstream over the tailplane, with a subsequent loss of some elevator authority.