Aviation Safety Investigation Report 199604036

Air Tractor Inc AT-502

10 December 1996

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at www.atsb.gov.au.

The Bureau did not conduct an on scene investigation of this occurrence. The information presented below was obtained from information supplied to the Bureau.

199604036	Occurrence Ty	pe: Accident
'Iffley' via Collarenabri		
NSW	Inv Category:	4
Tuesday 10 December 1996		
0105 hours	Time Zone	ESuT
Highest Injury Level: None		
AT-502 VH-CJZ	riculture - Other	Serial Number: 502-0026
	NSW Tuesday 10 December 1996 0105 hours None r: Air Tractor Inc AT-502 VH-CJZ Commercial Aerial Ag Destroyed Collarenebri NSW	'Iffley' via Collarenabri NSW Inv Category: Tuesday 10 December 1996 0105 hours Time Zone None r: Air Tractor Inc AT-502 VH-CJZ Commercial Aerial Agriculture - Other Destroyed Collarenebri NSW

Approved for Release: Wednesday, January 29, 1997

The Air Tractor 502 was conducting spraying operations late at night in fine conditions, with scattered cloud, no moon, and a barely discernable horizon. After levelling at approximately 200 ft from a pull up and procedure turn, the pilot reported that his attention was drawn to another aircraft which was spraying a nearby property. Whilst the pilot was watching the other aircraft the Air Tractor struck the ground at an estimated airspeed of 95 knots.

Wreckage distribution and pilot evidence indicated that, following the initial impact, the aircraft became airborne for a further 200 metres, with no engine or electrical power, before again striking the ground and sliding to a stop. The pilot, who had been wearing a full harness, escaped without injury. The aircraft was destroyed.