Aviation Safety Investigation Report 199500033

Robinson Helicopter Co R22

05 January 1995

Aviation Safety Investigation Report 199500033

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at www.atsb.gov.au.

The Bureau did not conduct an on scene investigation of this occurrence. The information presented below was obtained from information supplied to the Bureau.

Occurrence Number: 199500033 Occurrence Type: Accident

Location: Bankstown

State: NSW Inv Category: 4

Date: Thursday 05 January 1995

Time: 1110 hours **Time Zone** ESuT

Highest Injury Level: None

Aircraft Manufacturer: Robinson Helicopter Co

Aircraft Model: R22 BETA

Aircraft Registration: VH-JTH Serial Number: 1216

Type of Operation: Instructional Check

Damage to Aircraft:SubstantialDeparture Point:Camden NSWDeparture Time:1100 ESuT

Destination: Bankstown NSW

Crew Details:

RoleClass of LicenceHours on
Type Hours TotalPilot-In-CommandCommercial621.05352

Approved for Release: Friday, May 12, 1995

The pilot reported that during a practice engine off landing he flared the helicopter too high and the rotor RPM decayed, resulting in a heavy landing. Some slight buckling of the tail boom, firewall, and left side panel was evident after the landing.