

**Aviation Safety Investigation Report
199501834**

**Saab Aircraft AB
SF-340A**

13 June 1995

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at www.atsb.gov.au.

The Bureau did not conduct an on scene investigation of this occurrence. The information presented below was obtained from information supplied to the Bureau.

Occurrence Number: 199501834 **Occurrence Type:** Incident
Location: Wynyard, Aerodrome
State: TAS **Inv Category:** 4
Date: Tuesday 13 June 1995
Time: 0650 hours **Time Zone** EST
Highest Injury Level: None

Aircraft Manufacturer: Saab Aircraft AB
Aircraft Model: SF-340A
Aircraft Registration: VH-EKD **Serial Number:** 155
Type of Operation: Air Transport Domestic Low Capacity Passenger
Damage to Aircraft: Nil
Departure Point: Wynyard TAS
Departure Time: 0645 EST
Destination: Melbourne VIC

Approved for Release: Tuesday, October 29, 1996

Soon after takeoff the right engine suffered an underspeed condition and was shut down. The aircraft was returned to Wynyard for a single engine landing.

Maintenance investigation disclosed that the overspeed governor had failed. The governor was removed and sent to the manufacturer for assessment and repair. The manufacturer tested the governor, finding it to be noisy in operation. The high speed setting was found to be low, the governor was uncontrollable at the balance point and was unable to give an overspeed flow.

When the unit was stripped small pieces of aluminium were found in the solenoid body, along with other non metallic particles. The manufacturer did not detail the origin of the contaminants.

A series of failures to governors, pitch control units and feathering solenoid valves fitted to this aircraft type has been traced to electrokinetic corrosion and a particular brand of propeller gearbox oil. The operator has changed to a different oil and incorporated a manufacturer's modification designed to gain equal electrostatic potential by improving the bonding between the propeller and gearbox.

The operator advised that these measures appear to have reduced the rate of deterioration of the components.