Aviation Safety Investigation Report 199503011

Bell Helicopter Co 47G-3B-1 Soloy

28 August 1995

Aviation Safety Investigation Report 199503011

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at www.atsb.gov.au.

The Bureau did not conduct an on scene investigation of this occurrence. The information presented below was obtained from information supplied to the Bureau.

Occurrence Number: 199503011 Occurrence Type: Accident

Location: Rolleston, (ALA)

State: QLD Inv Category: 4

Date: Monday 28 August 1995

Time: 1330 hours **Time Zone** EST

Highest Injury Level: None

Aircraft Manufacturer: Bell Helicopter Co

Aircraft Model: 47G-3B1

Aircraft Registration: VH-ANG Serial Number: 6558

Type of Operation: Non-commercial Aerial Mustering

Damage to Aircraft:SubstantialDeparture Point:Roma QLDDeparture Time:1100 ESTDestination:Rolleston QLD

Crew Details:

	Hours on		
Role	Class of Licence	Type Hou	ırs Total
Pilot-In-Command	Commercial	225.0	300

Approved for Release: Monday, September 25, 1995

Soon after lifting off, the helicopter yawed suddenly to the right. There was no response to rudder inputs by the pilot but he was able to hold the heilcopter in a level attitude as it descended to the ground. The main rotor blades came into contact with the boom and both skids were bent during the ground impact. The pilot was able to safely exit the aircraft. Later examination found that the rear most section of the tail rotor drive shaft had disconnected at the tail rotor gearbox input.