Aviation Safety Investigation Report 199503035

Air Tractor Inc AT-301

12 September 1995

Aviation Safety Investigation Report 199503035

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at www.atsb.gov.au.

The Bureau did not conduct an on scene investigation of this occurrence. The information presented below was obtained from information supplied to the Bureau.

Occurrence Number: 199503035 Occurrence Type: Accident

Location: 9km NW Cleve, Aerodrome

State: SA Inv Category: 4

Date: Tuesday 12 September 1995

Time: 1745 hours **Time Zone** CST

Highest Injury Level: None

Aircraft Manufacturer: Air Tractor Inc

Aircraft Model: AT-301

Aircraft Registration: VH-JAI Serial Number: 301-0579

Type of Operation: Commercial Aerial Agriculture - Other

Damage to Aircraft: Substantial **Departure Point:** Cleve SA

Departure Time:

Destination: Cleve SA

Crew Details:

	Hours on		
Role	Class of Licence	Type Ho	urs Total
Pilot-In-Command	Commercial	500.0	3100

Approved for Release: Tuesday, February 20, 1996

The aircraft was engaged on agricultural operations in hilly country when it encountered a sink conditions.

Although the pilot applied full power and take-off flap, he was unable to prevent the aircraft from descending into trees tops on a ridgeline. The pilot dumped the load, but the aircraft continued to descend and impact the ground.

The pilot had not been aware of any sink indications during previous spray runs.