Aviation Safety Investigation Report 199503966

British Aerospace Plc Jetstream

30 September 1995

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at www.atsb.gov.au.

The Bureau did not conduct an on scene investigation of this occurrence. The information presented below was obtained from information supplied to the Bureau.

Occurrence Number:	199503966	Occurrence Type:	Incident	
Location:	Sydney			
State:	NSW	Inv Category:	4	
Date:	Saturday 30 September 1995			
Time:	1240 hours	Time Zone	EST	
Highest Injury Level:	None			
Aircraft Manufacture Aircraft Model: Aircraft Registration: Type of Operation: Damage to Aircraft: Departure Point: Departure Time: Destination:	 er: British Aerospace Plc 3107 VH-TQL Air Transport Domestic I Nil Williamtown NSW 1207 EST Sydney NSW 	Low Capacity Passer	nger Scheduled	Serial Number: 707

Crew Details:

	Hours on		
Role	Class of Licence	Туре Но	urs Total
Pilot-In-Command	ATPL	524.0	12070

Approved for Release: Wednesday, August 21, 1996

A Jetstream 31 aircraft was inbound to Sydney runway 34, on descent from 6,000 ft to 4,000 ft, when severe turbulence was encountered. Whilst being subjected to sustained buffeting, the aircraft experienced uncommanded pitch and roll events. Both pilots responded on the controls, in an attempt to minimise the excursions. At the crew's request, the air traffic controller advised that their separation from a preceding Airbus A300, also tracking for runway 34, was six miles.

Examination of recorded radar information confirmed that the required wake turbulence avoidance separation standard had been maintained. At the time at which the Jetstream 31 had experienced the upset, the A300 was 6.3 NM ahead. However, when closest to the point at which the upset occurred, the A300 had been 600 ft higher than the Jetstream, and the flight path of the A300 had been about 1 NM upwind of that of the Jetstream.

The effect of the prevailing wind, and the descent of the Jetstream to an altitude of less than 1,000 ft below that of the A300, placed the significantly smaller aircraft in the wake turbulence generated by the wide bodied aircraft.