Aviation Safety Investigation Report 199400844

Robinson Helicopter Co R22

06 April 1994

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at www.atsb.gov.au.

Occurrence Number:	199400844	Occurrence Type:	Accident
Location:	Cremorne Station (72km W Clerr	mont)	
State:	QLD	Inv Category:	4
Date:	Wednesday 06 April 1994		
Time:	1115 hours	Time Zone	EST
Highest Injury Level:	None		
Aircraft Manufacture	r: Robinson Helicopter Co		
Aircraft Model:	R22 BETA		
Aircraft Registration:	VH-LOA	Serial Number: 0943	5
Type of Operation:	Commercial Aerial Musterin	ng	
Damage to Aircraft:	Substantial		
Departure Point:	Cremorne Station QLD		
Departure Time:	0800 EST		
Destination:	Cremorne Station QLD		
Crew Details:			

	Hours on		
Role	Class of Licence	Туре Но	ours Total
Pilot-In-Command	Commercial	4025.0	13727

Approved for Release: Tuesday, September 20, 1994

During a cattle muster along a laneway, the pilot positioned the helicopter to head off a beast which broke away from the mob. As he descended in front of and to one side of the beast, he felt a sudden vibration through the helicopter and at the same time noticed an overhead powerline.

He lowered the collective for an immediate landing. The landing which followed was heavy, spreading and breaking the skid gear. The helicopter then rolled onto its side. Post flight inspection by the pilot revealed that the tail rotor had struck the wire.

The powerline was a single wire earth return line strung about 35 ft above ground. The span was reported to be 800 m long. The wire was struck some 100 m from the nearest pole which was partially hidden among foliage.