

**Aviation Safety Investigation Report  
199400927**

**Fokker B.V.  
F50 (Fokker 50)**

**07 April 1994**

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

**NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at [www.atsb.gov.au](http://www.atsb.gov.au).**

The Bureau did not conduct an on scene investigation of this occurrence. The information presented below was obtained from information supplied to the Bureau.

<b>Occurrence Number:</b>	199400927	<b>Occurrence Type:</b>	Incident
<b>Location:</b>	Albury		
<b>State:</b>	NSW	<b>Inv Category:</b>	4
<b>Date:</b>	Thursday 07 April 1994		
<b>Time:</b>	1100 hours	<b>Time Zone</b>	EST
<b>Highest Injury Level:</b>	None		

<b>Aircraft Manufacturer:</b>	Fokker B.V.		
<b>Aircraft Model:</b>	F27 MK 50		
<b>Aircraft Registration:</b>	VH-FNC	<b>Serial Number:</b>	20108
<b>Type of Operation:</b>	Air Transport	Domestic High Capacity Passenger	
<b>Damage to Aircraft:</b>	Nil		
<b>Departure Point:</b>	Albury NSW		
<b>Departure Time:</b>	1100 EST		
<b>Destination:</b>	Sydney NSW		

**Approved for Release:** Tuesday, August 30, 1994

The takeoff was rejected when the left engine torque indication was noted to be 13% below target torque. The subsequent investigation found that a fuel control unit drive shaft seal failure had allowed fuel to wash the lubrication from the shaft bearings which then failed. The drive shaft and spacer were badly worn and had caused a restriction to the governor flyweights which had signalled the lower torque during takeoff.