Aviation Safety Investigation Report 199400956

Cessna Aircraft Company Centurion

16 April 1994

Aviation Safety Investigation Report 199400956

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at www.atsb.gov.au.

The Bureau did not conduct an on scene investigation of this occurrence. The information presented below was obtained from information supplied to the Bureau.

Occurrence Number: 199400956 Occurrence Type: Accident

Location: Gove

State: NT Inv Category: 4

Date: Saturday 16 April 1994

Time: 1530 hours **Time Zone** CST

Highest Injury Level: None

Aircraft Manufacturer: Cessna Aircraft Company

Aircraft Model: 210M

Aircraft Registration: VH-AQH Serial Number: 21062846

Type of Operation: Miscellaneous Ferry

Damage to Aircraft:SubstantialDeparture Point:Milingimbi NTDeparture Time:1455 CST

Destination: Elcho Island NT

Crew Details:

	Hours on		
Role	Class of Licence	Type Hou	ırs Total
Pilot-In-Command	Commercial	21.5	194

Approved for Release: Friday, August 26, 1994

When the pilot selected the landing gear down in the circuit area the gear down light failed to illuminate. He recycled the landing gear then carried out the emergency extension procedures, but without success. The aircraft was fitted with a mirror and the pilot was able to observe that although the main landing gear appeared to be down and locked, the nose landing gear had not extended.

The pilot decided to divert to Gove and advised Adelaide Flight Service of his intentions. He requested that Emergency Services be made available.

On arrival in the circuit area the pilot discussed the problem with company engineers, then over a period of about 30 minutes made several unsuccessful attempts to extend the nose landing gear.

When the Emergency Services were in place, the pilot made an approach to runway 13. He shut down the engine on short finals, landed on the main wheels and held the nose up as long as possible. As the airspeed decreased, the nose dropped and slid along the runway, damaging the propeller and nose cowls.

Subsequent investigation revealed that the nose gear doors were jamming and had trapped the nose landing gear in the up position. The aircraft had suffered a landing gear collapse during a takeoff run some months previously and had only been flown a few hours in the two months since the repair. The nose landing gear doors had been causing extension problems during that time which had not been correctly rectified.