Aviation Safety Investigation Report 199401989

Cessna Aircraft Company Skyhawk

23 July 1994

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at www.atsb.gov.au.

The Bureau did not conduct an on scene investigation of this occurrence. The information presented below was obtained from information supplied to the Bureau.

Occurrence Number:	199401989	Occurrence Type	: Accident
Location:	Mount Windsor Station		
State:	QLD	Inv Category:	4
Date:	Saturday 23 July 1994		
Time:	1100 hours	Time Zone	EST
Highest Injury Level: None			
Aircraft Manufacture Aircraft Model: Aircraft Registration: Type of Operation: Damage to Aircraft: Departure Point: Departure Time:	er: Cessna Aircraft Co 172P VH-BFQ Commercial Ae Substantial Mount Windsor QI	Serial rial Mustering LD	Number: 17274943
Destination:	Mount Windsor QI	LD	

Approved for Release: Wednesday, February 15, 1995

The pilot reported that during the take-off run he became apprehensive about the runway distance remaining. The take-off was abandoned but the aircraft collided with a fence.

The pilot said that the runway surface was covered with small pebbles which appeared to reduce the braking efficiency. He steered the aircraft to the right to avoid a fence. The aircraft was almost stationary when it struck the fence.