

**Aviation Safety Investigation Report  
199402191**

**Saab Aircraft AB  
340**

**05 August 1994**

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

**NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at [www.atsb.gov.au](http://www.atsb.gov.au).**

The Bureau did not conduct an on scene investigation of this occurrence. The information presented below was obtained from information supplied to the Bureau.

**Occurrence Number:** 199402191      **Occurrence Type:** Incident  
**Location:** Cudal  
**State:** NSW      **Inv Category:** 4  
**Date:** Friday 05 August 1994  
**Time:** 0700 hours      **Time Zone:** EST  
**Highest Injury Level:** None

**Aircraft Manufacturer:** Saab Aircraft AB  
**Aircraft Model:** SF-340B  
**Aircraft Registration:** VH-TCH      **Serial Number:** 362  
**Type of Operation:** Air Transport Domestic Low Capacity Passenger  
**Damage to Aircraft:** Nil  
**Departure Point:** Cudal NSW  
**Departure Time:** 0700 EST  
**Destination:** Orange NSW

**Approved for Release:** Monday, May 8, 1995

During take off the crew noticed a small surge on the right engine torque indicator, with no noticeable power change. Shortly after lift off, as the landing gear was retracting, the right engine torque suddenly increased to 107%. The power lever, although extremely stiff to move, was eventually retarded until the torque was reduced to 85%. By this time the auto coarsen system had commanded the propeller RPM to zero and the engine was shut down. The flight continued to Orange where an uneventful single engine landing was carried out.

Subsequent investigation revealed the right engine Beta tube had failed where it entered the Propeller Control Unit (PCU). The remains of the tube were jammed in the PCU, which was stiff to operate at the power lever input shaft.

Investigation by the manufacturer attributed the failure to localised pick up and seizure of the PCU Beta Sleeve to the Beta Tube Unit Sleeve, resulting from a reduction below the minimum diametrical clearance between the two components. This was due to an incorrectly formed undercut in the Beta Rack during manufacture, which prevented satisfactory location between the two components, and subsequent distortion of the sleeve.

The manufacturer has instigated an inspection requirement for Beta Racks from the same batch number and advised that future batches will be examined prior to assembly.