Aviation Safety Investigation Report 199402726

Piper Aircraft Corp Tomahawk

26 September 1994

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at www.atsb.gov.au.

The Bureau did not conduct an on scene investigation of this occurrence. The information presented below was obtained from information supplied to the Bureau.

Occurrence Number:	199402726	Occurrence Type	: Accident	
Location:	Archerfield			
State:	QLD	Inv Category:	4	
Date:	Monday 26 September 199	94		
Time:	0954 hours	Time Zone	EST	
Highest Injury Level: None				
Aircraft Manufacture Aircraft Model: Aircraft Registration: Type of Operation: Damage to Aircraft: Departure Point: Departure Time: Destination: Crew Details:	PA-38-112	al Number: 38-79A	1073	
		Hour	s on	

	Hours on		
Role	Class of Licence	Type Hours	s Total
Pilot-In-Command	Student	10.0	10

Approved for Release: Tuesday, March 12, 1996

The pilot was a student on his second solo flight. During the approach and roundout phase of the second circuit, the aircraft ballooned. The student pushed the controls forward and a heavy landing, nosewheel first, eventuated. The nose gear collapsed and the propeller struck the runway. The aircraft slewed to the right and came to rest within the flight strip.