Aviation Safety Investigation Report 199402734

Cessna Aircraft Company Skyhawk

25 September 1994

Aviation Safety Investigation Report 199402734

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at www.atsb.gov.au.

The Bureau did not conduct an on scene investigation of this occurrence. The information presented below was obtained from information supplied to the Bureau.

Occurrence Number: 199402734 Occurrence Type: Accident

Location: Cairns

State: QLD Inv Category: 4

Date: Sunday 25 September 1994

Time: 1030 hours **Time Zone** EST

Highest Injury Level: None

Aircraft Manufacturer: Cessna Aircraft Company

Aircraft Model: 172N

Aircraft Registration: VH-AKZ Serial Number: 17269751

Type of Operation: Non-commercial Pleasure/Travel

Damage to Aircraft:SubstantialDeparture Point:Cairns QldDeparture Time:0920 ESTDestination:Cairns Qld

Crew Details:

Role Class of Licence Type Hours Total
Pilot-In-Command Private 87.9 177

Approved for Release: Wednesday, February 15, 1995

The aircraft ballooned during the flare out to land. In attempting to correct the flare, the pilot pushed forward the control column which resulted in the aircraft landing heavily and the nosewheel and propeller striking the runway. The pilot appears to have reacted spontaneously by pushing the control column forward instead of overshooting from the approach. The pilot's low aeronautical experience may have contributed to his actions.