

**Aviation Safety Investigation Report  
199300818**

**Boeing Co  
B737-400**

**11 April 1993**

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

**NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at [www.atsb.gov.au](http://www.atsb.gov.au).**

**Occurrence Number:** 199300818      **Occurrence Type:** Incident  
**Location:** Cairns  
**State:** QLD      **Inv Category:** 3  
**Date:** Sunday 11 April 1993  
**Time:** 2040 hours      **Time Zone** EST  
**Highest Injury Level:** None

**Aircraft** Boeing Co  
**Manufacturer:**  
**Aircraft Model:** 737-476  
**Aircraft Registration:** VH-TJO      **Serial Number:** 24440  
**Type of Operation:** Air Transport Domestic High Capacity Passenger  
Scheduled  
**Damage to Aircraft:** Nil  
**Departure Point:** Brisbane QLD  
**Departure Time:** 1848 EST  
**Destination:** Cairns QLD

**Crew Details:**

<b>Role</b>	<b>Class of Licence</b>	<b>Hours on Type</b>	<b>Hours Total</b>
Pilot-In-Command	ATPL 1st Class	3260.0	12380

**Approved for Release:** Friday, October 8, 1993

Approaching Cairns the crew received the automatic terminal information service which gave the following information: "runway 15, wet, wind 170 degrees 12 knots, QNH 1014, temperature 22, 3 okta (cloud) at 2,500ft, lower patches, showers in area." Following a Distance Measuring Equipment (DME) arrival, the crew reported visual with the field at four nautical miles. They flew a visual circuit, tracking via a left downwind for runway 15.

During the base turn, the crew lost visual contact with the runway lights because a rain shower was positioned across the final approach path. The flying pilot (first officer) initiated an overshoot and commenced a right turn towards high terrain. The turn continued through some 250 degrees to 090 degrees magnetic, heading out to sea. The crew then conducted an instrument approach to runway 15 followed by a normal landing .

The right turn conducted by the crew allowed the aircraft to track outside the circling area limit of 4.2nm (7.8km). During the turn the lowest altitude of the aircraft was approximately 1,400ft in an area where the radar lowest safe altitude is 3,300ft.

The investigation revealed that the crew were under two misapprehensions. Both pilots believed that they would stay in visual meteorological conditions during the missed approach by conducting a right turn, although they had no way of assuring this on a dark night. The crew also thought that they were further off the coast (hence clear of high terrain) than they were. Prior to commencing the circuit the crew did not foresee the possibility of a missed approach and did not brief for that eventuality.

The procedures laid down in the Aeronautical Information Publication indicate that the crew should have remained inside the manoeuvring area for the DME arrival procedure following the loss of visual reference with the runway approach lights at night. This could best have been accomplished by continuing the left turn to intercept the 040 degree radial, whilst at the same time commencing a climb to the lowest safe altitude of 5,000ft (the procedure laid down for a missed approach off a DME Arrival).

#### FACTORS

1. The crew did not brief for the possibility of a missed approach in the circuit considering that rain showers were in the area.
2. They made a spontaneous, inappropriate decision to turn right thus tracking near high terrain.