

**Aviation Safety Investigation Report
199301537**

**Hughes Helicopters
Hughes 269**

30 May 1993

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at www.atsb.gov.au.

The Bureau did not conduct an on scene investigation of this occurrence. The information presented below was obtained from information supplied to the Bureau.

Occurrence Number: 199301537 **Occurrence Type:** Accident
Location: Brookdale Station
State: QLD **Inv Category:** 4
Date: Sunday 30 May 1993
Time: 0930 hours **Time Zone:** EST
Highest Injury Level: None

Aircraft Manufacturer: Hughes Helicopters
Aircraft Model: 269A
Aircraft Registration: VH-MAY **Serial Number:** 1181038
Type of Operation: Commercial Aerial Mustering
Damage to Aircraft: Substantial
Departure Point: Brookdale Station QLD
Departure Time: 0930 EST
Destination: Brookdale Station QLD

Crew Details:

| Role | Class of Licence | Hours on | |
|------------------|------------------|----------|-------------|
| | | Type | Hours Total |
| Pilot-In-Command | Commercial | 75.0 | 324 |

Approved for Release: Tuesday, October 12, 1993

The pilot stated that he had just refuelled the aircraft. The subsequent engine start and takeoff were normal. However, as the helicopter was accelerating through about 60 knots, the engine began to lose power, with decreasing RPM evident. As the pilot lowered the collective pitch control, the engine stopped. The pilot conducted an autorotation on to a road, but touched down in a high nose attitude and broke the right skid.

The engine had operated normally prior to the occurrence. The refuelling operation was the first from a newly opened drum but there was no indication of fuel contamination. Operation of the aircraft requires the fuel boost pump to be ON during takeoff and landing and when flying below 140 metres above ground level. The pilot was not certain that he had switched the pump on before takeoff. It is possible, therefore, that the engine failed due to fuel starvation.