



Occurrences Entered into the ATSB Aviation Safety Database  
Between 10 December 2011 and 16 December 2011

Occurrence Date	ATSB Reference Number	Occurrence Category	ATSB Investigation	Location	State	Aircraft Manufacturer	Aircraft Model	Operation Type	Operation Sub Type	Airspace Type	Airspace Class	ATSB Summary
19/10/10	201009232	Incident	No	Adelaide Aerodrome	SA	FAIRCHILD INDUSTRIES INC	SA227-DC	Air Transport Low Capacity	Passenger	CTR	C	During final approach, the crew received a nose wheel steering warning, and continued the approach with the steering disengaged.
30/10/11	201107547	Incident	No	Gold Coast Aerodrome, 180° M 46Km	NSW	AGUSTA, SPA, COSTRUZIONI AERONAUTICHE	A109S	General Aviation-Unknown	Unknown	OCTA	G	During the flight, the pilot received an oil warning and shut down the right engine. The aircraft diverted to Ballina where engineers found that the oil pressure sender unit had failed.
30/10/11	201108459	Incident	No	near Sydney Aerodrome	NSW	AIRBUS INDUSTRIE	A320-232	Air Transport High Capacity	Passenger	CTA	C	During the descent, the aircraft experienced severe turbulence and a flight attendant received a minor injury.
16/11/11	201107941	Incident	No	near Cairns Aerodrome	QLD	DE HAVILLAND CANADA	DHC-8-102	Air Transport Low Capacity	Passenger	CTR	C	During the climb and descent, the crew received flight computer error messages multiple times and the aircraft returned to Cairns. Engineers replaced the left air data computer.
17/11/11	201107951	Incident	No	Toowoomba Aerodrome	QLD	CESSNA AIRCRAFT COMPANY	R182	Aerial Work	Unknown	CTAF	G	During the approach, the pilot received an unsafe landing gear indication and conducted a missed approach. The aircraft landed after a fly-by inspection. During the landing roll, the nose landing gear collapsed. Engineers repositioned the down lock and fitted two new roll pins.
19/11/11	201108007	Incident	No	near Oakey Aerodrome	QLD	PIPER AIRCRAFT CORP	PA-25-235	Private	Other	OCTA	G	During the initial climb, the aircraft's engine lost power and the aircraft and the glider it was towing landed in a nearby paddock. An engineering inspection revealed that fuel exhaustion was the cause of the power loss.
20/11/11	201108039	Incident	No	near Lake Albert (VFR)	VIC	CESSNA AIRCRAFT COMPANY	177B	Private	Pleasure / Travel	OCTA	G	During cruise, the pilot observed two parachutists descending through the aircraft's flight path and turned to avoid them.
21/11/11	201108076	Incident	No	Gold Coast Aerodrome	QLD	AMATEUR BUILT AIRCRAFT	LANCAIR 320	General Aviation-Unknown	Unknown	CTR	C	During approach, the pilot reported an unsafe landing indication. Engineers could not find any faults with the landing gear.
23/11/11	201108087	Incident	No	Olympic Dam Aerodrome, 154° M 28Km	SA	FOKKER B.V.	F27 MK 50	Air Transport High Capacity	Passenger	OCTA	G	During descent, the automatic flight idle stop system became faulty and the aircraft returned to Adelaide. An engineering inspection revealed faulty radio altimeter antennae.
24/11/11	201108094	Incident	No	Sydney Aerodrome, W M 56Km	NSW	BRITISH AEROSPACE PLC	3201	Air Transport Low Capacity	Passenger	CTA	C	During the climb, the left attitude indicator failed. The aircraft was returned to Sydney. Engineers replaced the left attitude indicator.
24/11/11	201108117	Incident	No	Ballina/Byron Gateway Aerodrome, 062° M 22Km	NSW	Unknown	Unknown	Unknown	Unknown	OCTA	G	While the Airbus A320 was in a holding pattern an IFR aircraft in the vicinity did not track as expected. The A320 turned early to ensure that separation was maintained.
						AIRBUS INDUSTRIE	A320-232	Air Transport High Capacity	Passenger	CTA	C	
26/11/11	201108203	Incident	No	near Essendon Aerodrome	VIC	BEECH AIRCRAFT CORP	A36	Private	Unknown	CTR	C	During the approach, the pilot received an unsafe nose landing gear indication. The pilot conducted a missed approach and extended the gear manually. Engineers replaced the landing gear indicator light.
26/11/11	201108489	Incident	No	Warraber Island (ALA)	QLD	CESSNA AIRCRAFT COMPANY	208B	Air Transport Low Capacity	Passenger	CTAF	G	During the take-off run, the aircraft struck a pigeon.
27/11/11	201108208	Incident	No	Williamstown Aerodrome, 240° M 17Km	NSW	S.A.A.B. AIRCRAFT CO	340B	Air Transport Low Capacity	Passenger	CTA	C	Incomplete coordination details were passed on an aircraft approaching the airspace boundary.
27/11/11	201108214	Incident	No	Broome Aerodrome	WA	SHORT BROS PTY LTD	SC7-3 VARIANT 100	General Aviation-Unknown	Unknown	CTR	D	During the take-off run, the pilot received an abnormal engine indication and rejected the takeoff. An inspection revealed no fault with the engine.

NOTE: This document is based on unverified occurrence reports and is provided for information and guidance only. The data herein is dynamic and is therefore subject to change due to updated information. For the purpose of subsection 49(2) of the Transport Safety Investigation Act 2003 (TSI Act) any On-Board Recordings (OBR) relating to a matter the ATSB has decided not to investigate, as identified in this publication, are not to be treated as an OBR on and after the date of publication of this Weekly Summary. Section 48 of the Act contains a definition for an OBR. Part 6 Division 1 of the TSI Act provides for certain confidentiality protections which must be applied to OBRs.



Occurrences Entered into the ATSB Aviation Safety Database  
Between 10 December 2011 and 16 December 2011

Occurrence Date	ATSB Reference Number	Occurrence Category	ATSB Investigation	Location	State	Aircraft Manufacturer	Aircraft Model	Operation Type	Operation Sub Type	Airspace Type	Airspace Class	ATSB Summary
30/11/11	201108285	Incident	No	South Goulburn Island Aerodrome	NT	CESSNA AIRCRAFT COMPANY	441	Air Transport Low Capacity	Passenger	OCTA	G	The pilot received an abnormal right engine indication and shut down the engine prior to landing. Engineers found that the engine indication was false and replaced the right beta light switch.
30/11/11	201108317	Incident	No	near Canberra Aerodrome	ACT	BRITISH AEROSPACE PLC	BAE-125-1000B	Private	Unknown	CTA	C	During descent and final approach, the aircraft was struck by lightning and subsequently encountered severe turbulence and windshear. The aircraft sustained minor damage.
30/11/11	201108364	Incident	No	near Perth Aerodrome	WA	THE BOEING COMPANY	737-838	Air Transport High Capacity	Passenger	CTR	C	During the initial climb, the aircraft encountered severe turbulence.
30/11/11	201108467	Incident	No	Pearce Aerodrome	WA	BRITISH AEROSPACE PLC	Hawk 127	Military	Other		Unknown	During a post-flight maintenance inspection, evidence of a birdstrike was found. It could not be determined when the strike occurred.
1/12/11	201108278	Incident	No	Sydney Aerodrome, 242° M 37Km	NSW	S.A.A.B. AIRCRAFT CO	340B	Air Transport Low Capacity	Passenger	CTA	C	During the cruise, the crew reported an instrument failure. The engineering inspection revealed a faulty generator control unit.
1/12/11	201108311	Incident	No	Curtin Aerodrome	WA	AIRBUS INDUSTRIE	A320-212	Air Transport High Capacity	Passenger	CTAF	G	During the landing roll, the aircraft struck a bird.
1/12/11	201108331	Serious Incident	No	Parafield Aerodrome	SA	CESSNA AIRCRAFT COMPANY	172S	General Aviation-Unknown	Unknown	CTR	D	The pilot of the Cessna 172 made an early crosswind turn, passing in front of a Diamond DA42 which was turning downwind. Both aircraft took evasive action. ATC had not passed traffic to both aircraft.
						DIAMOND AIRCRAFT INDUSTRIES	DA 42	General Aviation-Unknown	Unknown			
1/12/11	201108332	Incident	No	Perth Aerodrome, E M 130Km	WA	FOKKER B.V.	F27 MK 50	Charter	Passenger	CTA	C	During cruise, the crew detected a communications problem. An engineering inspection revealed a sticky right push to talk (PTT) switch.
1/12/11	201108469	Incident	No	Pearce Aerodrome	WA	BRITISH AEROSPACE PLC	HAWK 127	Military	Other	PRD	PRD	During a post-flight inspection, evidence of a birdstrike was found. It could not be determined when the strike occurred.
1/12/11	201108481	Incident	No	Richmond (NSW) Aerodrome, 140° M 13Km	NSW	Unknown	Unknown	Unknown	Unknown	CTR	C	A helicopter entered controlled airspace without a clearance.
2/12/11	201108342	Incident	No	Adelaide Aerodrome	SA	Unknown	Unknown	Unknown	Unknown	CTR	C	The safety officer retrieved an Australian magpie carcass from the runway.
2/12/11	201108357	Incident	No	Mudgee Aerodrome	NSW	DASSAULT-AVIATION	FALCON 2000LX	Private	Pleasure / Travel	CTAF	G	The arriving Dassult Falcon descended below the agreed altitude resulting in a TCAS RA with the departing Dassult Falcon. The departing Falcon climbed to ensure separation.
						DASSAULT-AVIATION	FALCON 2000EX	Private	Pleasure / Travel	OCTA	G	
2/12/11	201108366	Incident	No	Cairns Aerodrome	QLD	CONVAIR	340	Flying Training	Other	CTR	C	Prior to departure, the crew received a right engine fire warning. An engineering inspection found no fault with the engine.
2/12/11	201108441	Incident	No	Melbourne Aerodrome	VIC							The safety officer retrieved a plastic object from the apron.
2/12/11	201108480	Incident	No	Richmond (NSW) Aerodrome, 120° M 19Km	NSW	CESSNA AIRCRAFT COMPANY	172S	Unknown	Unknown	CTR	C	The aircraft entered controlled airspace without a clearance.
2/12/11	201108553	Incident	No	EGATU (IFR)	Other	AIRBUS INDUSTRIE	A330-303	Air Transport High Capacity	Passenger	OCA	A	During the cruise, the primary heat exchanger plenum ruptured in the right air-conditioning pack.

NOTE: This document is based on unverified occurrence reports and is provided for information and guidance only. The data herein is dynamic and is therefore subject to change due to updated information. For the purpose of subsection 49(2) of the Transport Safety Investigation Act 2003 (TSI Act) any On-Board Recordings (OBR) relating to a matter the ATSB has decided not to investigate, as identified in this publication, are not to be treated as an OBR on and after the date of publication of this Weekly Summary. Section 48 of the Act contains a definition for an OBR. Part 6 Division 1 of the TSI Act provides for certain confidentiality protections which must be applied to OBRs.



Occurrences Entered into the ATSB Aviation Safety Database  
Between 10 December 2011 and 16 December 2011

Occurrence Date	ATSB Reference Number	Occurrence Category	ATSB Investigation	Location	State	Aircraft Manufacturer	Aircraft Model	Operation Type	Operation Sub Type	Airspace Type	Airspace Class	ATSB Summary
3/12/11	201108356	Incident	No	Sydney Aerodrome	NSW	THE BOEING COMPANY	737-8FE	Air Transport High Capacity	Passenger	CTR	C	The crew did not taxi in accordance with ATC instructions.
3/12/11	201108365	Incident	No	Jandakot Aerodrome	WA	AVIONS PIERRE ROBIN	R-2160	Unknown	Unknown	CTR	D	The aircraft struck a plover.
3/12/11	201108371	Incident	No	Adelaide Aerodrome	SA	THE BOEING COMPANY	737-476	Air Transport High Capacity	Passenger	CTR	C	During the take-off run, the aircraft struck a kestrel.
3/12/11	201108372	Incident	No	Sydney Aerodrome, NE M 6Km	NSW	ROBINSON HELICOPTER CO	R66	General Aviation-Unknown	Unknown	CTR	C	During climb, the pilot received an engine chip warning light and returned to Sydney. Engineers found a sliver of metal on the detector.
3/12/11	201108374	Serious Incident	No	near Emerald Aerodrome	QLD	Unknown	Unknown	Aerial Work	Aerial Agriculture	OCTA	G	It was reported that an aircraft struck powerlines.
3/12/11	201108375	Accident	No	West Sale Aerodrome	VIC	PIPER AIRCRAFT CORP	PA-28-161	Flying Training	Training Solo	CTAF	G	During the landing, the aircraft landed hard on the nose landing gear before bouncing multiple times. The aircraft sustained serious damage.
3/12/11	201108379	Incident	No	Geraldton Aerodrome	WA	Unknown GIPPSLAND AERONAUTICS PTY LTD	Unknown GA-8	Unknown Charter	Unknown Passenger	CTAF	G	During final approach, the Gippsland Aeronautics GA-8 pilot observed an aircraft backtracking on the runway and conducted a missed approach. The crew of the other aircraft advised that they had been operating on an incorrect radio frequency.
4/12/11	201108358	Incident	No	Brisbane Aerodrome	QLD	AIRBUS INDUSTRIE	A330-303	Air Transport High Capacity	Passenger	CTR	C	During the takeoff run, the co-pilot's speed display failed and the takeoff was rejected. As the aircraft decelerated, a tyre shredded. Engineers were unable to identify any faults in the airspeed display system.
4/12/11	201108367	Incident	No	Melbourne Aerodrome	VIC							During a runway inspection, the safety officer retrieved a spanner.
4/12/11	201108368	Incident	No	Adelaide Aerodrome, 330° M 74Km	SA	AIR TRACTOR INC	AT-502B	General Aviation-Unknown	Unknown	PRD	PRD	The aircraft entered restricted airspace without a clearance.
4/12/11	201108369	Incident	No	Brisbane Aerodrome	QLD	THE BOEING COMPANY	737-8FE	Air Transport High Capacity	Passenger	CTR	C	During the take-off run, the aircraft struck a nankeen kestrel.
4/12/11	201108370	Incident	No	Hazleton (ALA)	QLD	Jabiru	Unknown	General Aviation-Unknown	Unknown	OCTA	G	During the cruise, the engine began to run roughly and the pilot conducted a precautionary landing at Hazleton.
4/12/11	201108373	Incident	No	near Melbourne Aerodrome	VIC	THE BOEING COMPANY	737-8FE	Air Transport High Capacity	Passenger	CTR	C	During the initial climb, the cabin crew detected fumes in the aft cabin.
4/12/11	201108377	Incident	No	ONOXA (IFR)	Other	Unknown	Unknown	Air Transport High Capacity	Passenger	OCA	A	Incorrect coordination details were passed on an aircraft approaching the airspace boundary.
4/12/11	201108381	Incident	No	Caboolture (ALA), 190° M 9Km	QLD	BEECH AIRCRAFT CORP	A36	General Aviation-Unknown	Unknown	CTA	C	During climb, the aircraft diverted off track without a clearance and infringed an active parachute drop zone in which parachutists were operating. The pilot was immediately instructed to turn away from the drop zone.
4/12/11	201108383	Accident	No	Lower Light (ALA)	SA	CESSNA AIRCRAFT COMPANY	182E	Private	Parachute Operations	OCTA	G	During the landing roll on the short strip, the aircraft did not decelerate as expected. The pilot attempted to turn onto the crossing strip resulting in the aircraft sliding off the runway. The aircraft was substantially damaged.

NOTE: This document is based on unverified occurrence reports and is provided for information and guidance only. The data herein is dynamic and is therefore subject to change due to updated information. For the purpose of subsection 49(2) of the Transport Safety Investigation Act 2003 (TSI Act) any On-Board Recordings (OBR) relating to a matter the ATSB has decided not to investigate, as identified in this publication, are not to be treated as an OBR on and after the date of publication of this Weekly Summary. Section 48 of the Act contains a definition for an OBR. Part 6 Division 1 of the TSI Act provides for certain confidentiality protections which must be applied to OBRs.



Occurrences Entered into the ATSB Aviation Safety Database  
Between 10 December 2011 and 16 December 2011

Occurrence Date	ATSB Reference Number	Occurrence Category	ATSB Investigation	Location	State	Aircraft Manufacturer	Aircraft Model	Operation Type	Operation Sub Type	Airspace Type	Airspace Class	ATSB Summary
4/12/11	201108384	Incident	No	near Darwin Aerodrome	NT	CESSNA AIRCRAFT COMPANY	404	Air Transport Low Capacity	Passenger	CTR	C	During approach, the crew received an unsafe landing gear indication and conducted a missed approach. The crew recycled the landing gear and subsequently landed. Engineers replaced the right main landing gear actuator.
4/12/11	201108385	Incident	No	Bindook (NDB/VOR)	NSW	BOMBARDIER INC	DHC-8-402	Air Transport High Capacity	Passenger	CTA	C	While entering the holding pattern, the Bombardier DHC-8-402 descended below the assigned altitude resulting in a loss of separation with the Saab 340 in the holding pattern.
						S.A.A.B. AIRCRAFT CO	340B	Air Transport Low Capacity	Passenger			
4/12/11	201108386	Incident	No	near Caboolture (ALA)	QLD	Jabiru	J-160-D	Sports Aviation	Unknown	OCTA	G	During the climb, the aircraft's engine lost partial power. The crew conducted a precautionary landing at Hazelton.
4/12/11	201108387	Incident	No	Sydney Aerodrome, 335° M 19Km	NSW	FAIRCHILD INDUSTRIES INC	SA226-T	General Aviation-Unknown	Unknown	CTA	C	The aircraft did not track in accordance with ATC instructions
4/12/11	201108388	Incident	No	Launceston Aerodrome	TAS	FOKKER B.V.	F27 MK 50	Air Transport High Capacity	Passenger	CTR	D	During the take-off run, the crew received a configuration warning and rejected the takeoff. The inspection revealed that the auto-feather system was not arming with the power levers in the take-off detent. The engineering inspection found no faults.
4/12/11	201108389	Incident	No	LAMOB (IFR)	Other	AIRBUS INDUSTRIE	A340-313X	Air Transport High Capacity	Passenger	OCA	A	Incorrect coordination details were passed on an aircraft approaching the airspace boundary.
4/12/11	201108403	Incident	No	near Shark Bay Aerodrome	WA	CESSNA AIRCRAFT COMPANY	182H	Aerial Work	Survey / Photographic	CTAF	G	During aerial work, the pilot was not in normal communication with other traffic. It was discovered that the life jacket that the pilot was wearing had pushed the headset volume control setting to zero.
4/12/11	201108490	Incident	No	BIDAG (IFR)	QLD	CESSNA AIRCRAFT COMPANY	404	Charter	Passenger	CTA	C	During cruise, the passenger door opened and the aircraft returned to Cairns.
4/12/11	201108500	Incident	No	Sydney Aerodrome	NSW	AIRBUS INDUSTRIE	A330-303	Air Transport High Capacity	Passenger	CTR	C	During the unloading of the aircraft, incorrectly labelled dangerous goods (flammable gas) were detected.
5/12/11	201108376	Incident	No	ALEXA (IFR)	Other	S.A.A.B. Aircraft Co	340B	Air Transport Low Capacity	Passenger	OCTA	G	No coordination details were passed on an aircraft approaching the airspace boundary.
5/12/11	201108378	Incident	No	Melbourne Aerodrome, 155° M 20Km	VIC	PIPER AIRCRAFT CORP	PA-28R-200	General Aviation-Unknown	Unknown	CTA	C	The aircraft entered controlled airspace without a clearance.
5/12/11	201108380	Incident	No	Rockhampton Aerodrome, 122° M 56Km	QLD	MOONEY AIRCRAFT CORP	M20K	General Aviation-Unknown	Unknown	CTA	C	The pilot did not comply to the ATC tracking instruction.
5/12/11	201108390	Incident	No	Richmond (Qld) Aerodrome	QLD	S.A.A.B. AIRCRAFT CO	340B	Air Transport Low Capacity	Passenger	CTAF	G	During the takeoff, the aircraft struck two birds. The aircraft diverted to Townsville.
5/12/11	201108391	Incident	No	Learmonth Aerodrome	WA	LOCKHEED GEORGIA	P-3C	Military	Other	CTAF	G	DuDuring the initial climb, the aircraft struck a bird and returned to Learmonth.
5/12/11	201108392	Incident	No	Canberra Aerodrome	ACT	THE BOEING COMPANY	737-838	Air Transport High Capacity	Passenger	CTR	C	DuDuring the takeoff and initial climb, cabin crew detected fumes in the cabin which dissipated shortly after. Engineers were unable to identify the source.
5/12/11	201108394	Incident	No	Jandakot Aerodrome	WA	PILATUS AIRCRAFT LTD	PC-12/45	Charter	Unknown	CTR	D	The aircraft taxied without a clearance.

NOTE: This document is based on unverified occurrence reports and is provided for information and guidance only. The data herein is dynamic and is therefore subject to change due to updated information. For the purpose of subsection 49(2) of the Transport Safety Investigation Act 2003 (TSI Act) any On-Board Recordings (OBR) relating to a matter the ATSB has decided not to investigate, as identified in this publication, are not to be treated as an OBR on and after the date of publication of this Weekly Summary. Section 48 of the Act contains a definition for an OBR. Part 6 Division 1 of the TSI Act provides for certain confidentiality protections which must be applied to OBRs.



Occurrences Entered into the ATSB Aviation Safety Database  
Between 10 December 2011 and 16 December 2011

Occurrence Date	ATSB Reference Number	Occurrence Category	ATSB Investigation	Location	State	Aircraft Manufacturer	Aircraft Model	Operation Type	Operation Sub Type	Airspace Type	Airspace Class	ATSB Summary
5/12/11	201108395	Incident	No	Coonamble Aerodrome, NW M 11Km	NSW	PIPER AIRCRAFT CORP	PA-28-161	Flying Training	Training Dual	CTAF	G	During an approach, the aircraft struck a hawk.
5/12/11	201108396	Incident	No	Jandakot Aerodrome	WA	GROB - BURKHAART FLUGZEUGBAU	G-115C2	General Aviation-Unknown	Unknown	CTR	D	During taxi, the aircraft crossed a runway without a clearance.
5/12/11	201108397	Incident	No	near Broome Aerodrome	WA	CESSNA AIRCRAFT COMPANY	U206G	General Aviation-Unknown	Unknown	CTA	D	The aircraft climbed above the assigned altitude.
5/12/11	201108398	Incident	No	near Hong Kong International Airport	Other	AIRBUS INDUSTRIE	A330-303	Air Transport High Capacity	Passenger	Other	Foreign	During cruise, the pilot in command became incapacitated and the aircraft diverted to Hong Kong.
5/12/11	201108399	Incident	No	TIMET (IFR)	Other	The Boeing Co	777-31H/ER	Air Transport High Capacity	Passenger	CTA	A	The aircraft did not adhere to the height requirements of the block clearance.
5/12/11	201108400	Incident	No	near Perth Aerodrome	WA	EMBRAER-EMPRESA BRASILEIRA DE AERONAUTICA	EMB-120 ER	Charter	Passenger	CTA	C	During climb, the crew received an unsafe landing gear indication and returned to Perth.
5/12/11	201108407	Incident	No	Moorabbin Aerodrome	VIC	PIPER AIRCRAFT CORP	PA-28-161	General Aviation-Unknown	Unknown	CTR	D	The aircraft entered the runway without a clearance.
5/12/11	201108408	Incident	No	TAVEV (IFR)	QLD	AIRBUS INDUSTRIE	A330-323X	Air Transport High Capacity	Passenger	CTA	A	During the cruise, the crew did not update a waypoint estimate with the aircraft arriving eight minutes late.
5/12/11	201108410	Incident	No	Bankstown Aerodrome	NSW	BEECH AIRCRAFT CORP	58	General Aviation-Unknown	Unknown	CTA	C	The aircraft did not adhere to the heading requirement of the BANKSTOWN SIX DEPARTURE.
5/12/11	201108419	Incident	No	Melbourne Aerodrome	VIC	AIRBUS INDUSTRIE	A320	Air Transport High Capacity	Passenger	CTR	C	During boarding, a passenger sustained a minor injury.
5/12/11	201108420	Incident	No	SAPDA (IFR)	Other	AIRBUS INDUSTRIE	A330-202	Air Transport High Capacity	Passenger	OCA	A	No coordination details were passed on an aircraft approaching the airspace boundary.
5/12/11	201108421	Incident	No	near Perth Aerodrome	WA	THE BOEING COMPANY	737-838	Air Transport High Capacity	Passenger	CTA	C	The aircraft did not adhere to the height requirement of the PERTH RWY 06 VOR approach.
5/12/11	201108424	Incident	No	Melbourne Aerodrome	VIC	THE BOEING COMPANY	737-8FE	Air Transport High Capacity	Passenger	CTR	C	After landing, smoke was observed emanating from the left control column. Engineers found fluff in a switch mechanism.
5/12/11	201108427	Incident	No	Cairns Aerodrome	QLD							The runway lights extinguished for two seconds while an aircraft was in its landing roll.
5/12/11	201108429	Incident	No	Roma Aerodrome	QLD	BOMBARDIER INC	DHC-8-315	Air Transport High Capacity	Passenger	CTAF	G	After engine start, the right hydraulic system failed to pressurize. The right engine was shut down. Engineers replaced the right hydraulic shutoff actuator.
5/12/11	201108432	Incident	No	Parkes Aerodrome, E M 17Km	NSW	Unknown S.A.A.B. AIRCRAFT CO	Unknown 340B	Gliding Air Transport Low Capacity	Other Passenger	CTAF	G	During descent, the Saab 340 crew observed a glider passing below the aircraft. The glider pilot had not responded to radio calls.

NOTE: This document is based on unverified occurrence reports and is provided for information and guidance only. The data herein is dynamic and is therefore subject to change due to updated information. For the purpose of subsection 49(2) of the Transport Safety Investigation Act 2003 (TSI Act) any On-Board Recordings (OBR) relating to a matter the ATSB has decided not to investigate, as identified in this publication, are not to be treated as an OBR on and after the date of publication of this Weekly Summary. Section 48 of the Act contains a definition for an OBR. Part 6 Division 1 of the TSI Act provides for certain confidentiality protections which must be applied to OBRs.



Occurrences Entered into the ATSB Aviation Safety Database  
Between 10 December 2011 and 16 December 2011

Occurrence Date	ATSB Reference Number	Occurrence Category	ATSB Investigation	Location	State	Aircraft Manufacturer	Aircraft Model	Operation Type	Operation Sub Type	Airspace Type	Airspace Class	ATSB Summary
5/12/11	201108470	Incident	No	Pearce Aerodrome	WA	BRITISH AEROSPACE PLC	HAWK 127	Military	Other	PRD	PRD	During a post-flight maintenance inspection, evidence of a birdstrike was found. It could not be determined when the strike occurred.
5/12/11	201108474	Incident	No	East Sale Aerodrome, 235° M 57Km	VIC	LAKE A/C DIV. OF CONSOLIDATED AERONAUTICS INC.	LA-4-200	General Aviation-Unknown	Unknown	PRD	PRD	The aircraft entered restricted airspace without a clearance.
6/12/11	201108401	Incident	No	Sunshine Coast Aerodrome	QLD	PIPER AIRCRAFT CORP	PA-46-310P	General Aviation-Unknown	Unknown	CTR	D	The crew did not taxi in accordance with ATC instructions and the aircraft entered the runway without a clearance.
6/12/11	201108406	Incident	No	Melbourne Aerodrome	VIC	THE BOEING COMPANY	737-8FE	Air Transport High Capacity	Passenger	CTR	C	During the landing, the aircraft struck a bird.
6/12/11	201108409	Incident	No	near Canberra Aerodrome	ACT							The Sandra's View radar failed for ten minutes.
6/12/11	201108411	Incident	No	Gold Coast Aerodrome, 276° M 33Km	QLD	BELL HELICOPTER CO	212	General Aviation-Unknown	Unknown	PRD	PRD	The aircraft entered restricted airspace without a clearance.
6/12/11	201108412	Incident	No	Perth Aerodrome, 290° M 74Km	WA	Airbus Industrie	A340-313X	Air Transport High Capacity	Passenger	CTA	C	During the descent, the aircraft was struck by lightning. The crew also reported a low tyre pressure warning.
6/12/11	201108413	Incident	No	near Cairns Aerodrome	QLD	CESSNA AIRCRAFT COMPANY	208	General Aviation-Unknown	Unknown	CTA	C	The aircraft descended below its assigned level.
6/12/11	201108414	Incident	No	near Brisbane Aerodrome	QLD	BOMBARDIER INC	DHC-8-402	Air Transport High Capacity	Passenger	CTA	C	The aircraft turned onto an incorrect heading.
6/12/11	201108416	Incident	No	Maleny (VOR)	QLD	BOMBARDIER INC	DHC-8-402	Air Transport High Capacity	Passenger	CTA	C	During the approach, the left engine failed. Engineers found the accessory drive gearbox had become disconnected causing disruption to the fuel supply to the engine.
6/12/11	201108422	Incident	No	Horn Island Aerodrome	QLD	PIPER AIRCRAFT CORP	PA-32-300	Air Transport Low Capacity	Passenger	CTAF	G	While attempting to start the engine, the carburettor was over-primed and the excess fuel ignited in the air cleaner.
6/12/11	201108423	Incident	No	near Sydney Aerodrome	NSW	AIRBUS INDUSTRIE	A340-313X	Air Transport High Capacity	Passenger	CTA	C	The aircraft did not adhere to the tracking requirements of the SID.
6/12/11	201108430	Incident	No	near Tamworth Aerodrome	NSW	PACIFIC AEROSPACE CORPORATION	CT/4B	General Aviation-Unknown	Unknown	CTR	D	During the flight, the crew detected a carbon monoxide (CO) reading in the caution range. Engineers replaced all suspect taping and sealed all possible CO ingestion points.
6/12/11	201108435	Incident	No	Richmond (NSW) Aerodrome, 345° M 33Km	NSW	CESSNA AIRCRAFT COMPANY	172N	Charter	Unknown	PRD	PRD	The aircraft entered restricted airspace without a clearance.
6/12/11	201108436	Incident	No	Moorabbin Aerodrome	VIC	PIPER AIRCRAFT CORP	PA-44-180	General Aviation-Unknown	Unknown	CTR	D	During the initial climb from runway 17L, the aircraft turned right into the circuit area of runway 17R without a clearance.
6/12/11	201108437	Incident	No	POSOD (IFR), 154° M 37Km	Other	THE BOEING COMPANY	C-17	Military	Other	OCA	A	During the cruise, the aircraft diverted off track without a clearance and the crew were not in normal communications with ATC for 10 minutes..
6/12/11	201108438	Incident	No	Bankstown Aerodrome, 110° M 6Km	NSW	CESSNA AIRCRAFT COMPANY	441	General Aviation-Unknown	Unknown	CTR	C	The pilot did not turn in accordance with departure instructions resulting in the aircraft entering Sydney controlled airspace without a clearance.

NOTE: This document is based on unverified occurrence reports and is provided for information and guidance only. The data herein is dynamic and is therefore subject to change due to updated information. For the purpose of subsection 49(2) of the Transport Safety Investigation Act 2003 (TSI Act) any On-Board Recordings (OBR) relating to a matter the ATSB has decided not to investigate, as identified in this publication, are not to be treated as an OBR on and after the date of publication of this Weekly Summary. Section 48 of the Act contains a definition for an OBR. Part 6 Division 1 of the TSI Act provides for certain confidentiality protections which must be applied to OBRs.



Occurrences Entered into the ATSB Aviation Safety Database  
Between 10 December 2011 and 16 December 2011

Occurrence Date	ATSB Reference Number	Occurrence Category	ATSB Investigation	Location	State	Aircraft Manufacturer	Aircraft Model	Operation Type	Operation Sub Type	Airspace Type	Airspace Class	ATSB Summary
6/12/11	201108439	Incident	No	Kowanyama Aerodrome	QLD	AERO COMMANDER	500-S	Charter	Unknown	CTAF	G	During the landing roll, the aircraft struck a bird.
6/12/11	201108442	Incident	No	Narrabri Aerodrome	NSW	BRITISH AEROSPACE PLC	3201	Air Transport Low Capacity	Passenger	CTAF	G	During the landing roll, the aircraft struck two galahs.
6/12/11	201108445	Incident	No	Melbourne Aerodrome	VIC							The safety officer retrieved a screwdriver from runway 34.
6/12/11	201108446	Incident	No	near Perth Aerodrome	WA	DE HAVILLAND CANADA	DHC-8-102	Charter	Passenger	CTA	C	During the approach, the aircraft was struck by lightning.
6/12/11	201108447	Incident	No	near Perth Aerodrome	WA	THE BOEING COMPANY	767-338	Air Transport High Capacity	Passenger	CTR	C	During the approach, the aircraft was struck by lightning.
6/12/11	201108448	Incident	No	WEENA (IFR)	Other	THE BOEING COMPANY	777-219	Air Transport High Capacity	Passenger	OCA	A	Incorrect coordination details were passed on an aircraft approaching the airspace boundary.
6/12/11	201108449	Incident	No	Boulia Aerodrome	QLD	DE HAVILLAND CANADA	DHC-8-102	Air Transport Low Capacity	Passenger	CTAF	G	During the take-off run, the aircraft struck a whistling kite (bird).
6/12/11	201108453	Incident	No	overhead Singleton (NDB)	NSW	PIPER AIRCRAFT CORP	PA-31-350	Charter	Passenger	OCTA	G	During cruise, the right alternator failed and the aircraft diverted to Scone. An investigation revealed a broken wire.
6/12/11	201108460	Incident	No	Amberley Aerodrome	QLD	THE BOEING COMPANY	F/A-18E	Military	Other	CTR	C	During the initial climb, the aircraft struck a bat.
6/12/11	201108461	Incident	No	Brisbane Aerodrome, 196° M 15Km	QLD	BEECH AIRCRAFT CORP	76	Flying Training	Training Dual	CTA	C	During the cruise, the landing gear in-transit light illuminated. The crew performed a manual landing gear extension. The engineering inspection reported a faulty hydraulic valve.
6/12/11	201108464	Incident	No	Melbourne Aerodrome	VIC	THE BOEING COMPANY	737-838	Air Transport High Capacity	Passenger	CTR	C	During the approach, the aircraft encountered moderate overshoot windshear.
6/12/11	201108466	Incident	No	near Melbourne Aerodrome	VIC	AIRBUS INDUSTRIE	A380-842	Air Transport High Capacity	Passenger	CTA	A	During the climb, the crew received fuel quantity management system (FQMS) warnings and the number-four fuel crossfeed valve failed to open, resulting in low fuel quantity in that tank. An engineering inspection revealed no faults with the fuel system.
6/12/11	201108472	Incident	No	Edinburgh Aerodrome	SA	LOCKHEED GEORGIA	P-3C	Military	Other	CTR	C	During final approach, the aircraft struck a bird.
6/12/11	201108476	Incident	No	East Sale Aerodrome, 210° M 33Km	VIC	CESSNA AIRCRAFT COMPANY	172S	Unknown	Unknown	PRD	PRD	The aircraft entered restricted airspace without a clearance.
6/12/11	201108492	Incident	No	DIPSO (IFR)	NSW	THE BOEING COMPANY	747-422	Air Transport High Capacity	Passenger	CTA	C	During cruise, the aircraft entered a restricted airspace buffer zone without a clearance resulting in a loss of separation assurance.
7/12/11	201108347	Incident	No	Learmonth Aerodrome	WA	FOKKER B.V.	F28 MK 0100	Air Transport High Capacity	Passenger	CTAF	G	During initial climb, the aircraft received a windshear warning. The crew selected full throttle and continued the climb. The windshear alert ceased passing 1,500 ft.
7/12/11	201108433	Incident	No	Melbourne Aerodrome	VIC	THE BOEING COMPANY	737-8BK	Air Transport High Capacity	Passenger	CTR	C	During the take-off, and again during landing, the crew detected fumes in the cockpit and forward cabin. An engineering inspection revealed the source of the fumes to be excess oil added during recent servicing.
7/12/11	201108444	Incident	No	Mount Cottrell (VFR)	VIC	CESSNA AIRCRAFT COMPANY	182T	General Aviation-Unknown	Unknown	CTA	C	The aircraft entered controlled airspace without a clearance.

NOTE: This document is based on unverified occurrence reports and is provided for information and guidance only. The data herein is dynamic and is therefore subject to change due to updated information. For the purpose of subsection 49(2) of the Transport Safety Investigation Act 2003 (TSI Act) any On-Board Recordings (OBR) relating to a matter the ATSB has decided not to investigate, as identified in this publication, are not to be treated as an OBR on and after the date of publication of this Weekly Summary. Section 48 of the Act contains a definition for an OBR. Part 6 Division 1 of the TSI Act provides for certain confidentiality protections which must be applied to OBRs.



Occurrences Entered into the ATSB Aviation Safety Database  
Between 10 December 2011 and 16 December 2011

Occurrence Date	ATSB Reference Number	Occurrence Category	ATSB Investigation	Location	State	Aircraft Manufacturer	Aircraft Model	Operation Type	Operation Sub Type	Airspace Type	Airspace Class	ATSB Summary
7/12/11	201108450	Incident	No	CULIN (IFR)	NSW	THE BOEING COMPANY	737-838	Air Transport High Capacity	Passenger	CTA	A	The aircraft entered the holding pattern at the incorrect waypoint.
7/12/11	201108451	Incident	No	Melbourne Aerodrome, 243° M 54Km	VIC	CESSNA AIRCRAFT COMPANY	150M	General Aviation-Unknown	Unknown	CTA	C	The aircraft entered controlled airspace without a clearance.
7/12/11	201108455	Incident	No	Bacchus Marsh (ALA), S M 6Km	VIC	Flysynthesis	Texan TC	Sports Aviation	Unknown	CTA	C	The aircraft entered controlled airspace without a clearance.
7/12/11	201108456	Incident	No	Brighton (VFR)	VIC	PIPER AIRCRAFT CORP	PA-28-151	General Aviation-Unknown	Unknown	CTA	C	The aircraft entered controlled airspace without a clearance.
7/12/11	201108457	Incident	No	Perth Aerodrome, W M 11Km	WA	VULCANAIR S.P.A.	P.68C	General Aviation-Unknown	Unknown	CTR	C	During the cruise, the aircraft diverted off track without a clearance.
7/12/11	201108458	Incident	No	Moorabbin Aerodrome, 170° M 6Km	VIC	CESSNA AIRCRAFT COMPANY	172P	General Aviation-Unknown	Unknown	CTR	D	The aircraft entered controlled airspace without a clearance. The pilot was transmitting on an incorrect frequency.
7/12/11	201108465	Incident	No	Adelaide Aerodrome	SA	S.A.A.B. AIRCRAFT CO	340B	Air Transport Low Capacity	Passenger	CTR	C	During the landing, the aircraft struck a magpie lark.
7/12/11	201108468	Incident	No	Learmonth Aerodrome	WA	Lockheed Corporation	P-3C	Military	Other	CTAF	G	During the landing roll, the aircraft struck a bird.
7/12/11	201108471	Incident	No	Bundaberg Aerodrome, 145° M 24Km	QLD	CESSNA AIRCRAFT COMPANY	560	Unknown	Unknown	CTA	E	The aircraft entered controlled airspace without a clearance.
7/12/11	201108473	Incident	No	Coffs Harbour Aerodrome	NSW	CESSNA AIRCRAFT COMPANY	182L	General Aviation-Unknown	Unknown	CTR	D	The crew did not taxi in accordance with ATC instructions and the aircraft entered the runway without a clearance.
7/12/11	201108475	Incident	No	Moorabbin Aerodrome	VIC	PIPER AIRCRAFT CORP	PA-28-161	General Aviation-Unknown	Unknown	CTR	D	The crew did not taxi in accordance with ATC instructions and the aircraft entered the runway without a clearance.
7/12/11	201108477	Incident	No	BAXMN (IFR)	WA	FOKKER B.V.	F28 MK 0100	Charter	Passenger	CTA	A	No coordination details were passed on an aircraft approaching the airspace boundary.
7/12/11	201108478	Incident	No	Charleville Aerodrome	QLD	DE HAVILLAND CANADA	DHC-8-202	Air Transport Low Capacity	Passenger	CTAF	G	During the landing roll, the aircraft struck a bird.
7/12/11	201108479	Serious Incident	No	Perth Aerodrome, 210° M 50Km	WA	SPORTAVIA PUTZER GMBH	RF4D FOURNIER	Sports Aviation	Other	OCTA	G	While conducting aerobatics, the engine failed and the pilot conducted a forced landing. On inspection, an insect was found lodged in the carburettor main-jet.
7/12/11	201108482	Incident	No	overhead Guam international Airport	Other	AIRBUS INDUSTRIE	A330-202	Air Transport High Capacity	Passenger	OCA	A	During the cruise, the aircraft encountered turbulence and a flight attendant sustained a minor injury.
7/12/11	201108483	Incident	No	Perth Aerodrome	WA	Unknown	Unknown	Unknown	Unknown	CTR	C	During a runway inspection, the safety officer removed two black cockatoo carcasses.
7/12/11	201108486	Incident	No	overhead Taroom Aerodrome	QLD	FOKKER B.V.	F28 MK 0100	Air Transport High Capacity	Passenger	CTA	A	During the cruise, the aircraft's windscreen cracked and the aircraft returned to Brisbane.
7/12/11	201108487	Incident	No	near Brisbane Aerodrome	QLD	THE BOEING COMPANY	737-838	Air Transport High Capacity	Passenger	CTR	C	During the descent, the aircraft was struck by lightning.

NOTE: This document is based on unverified occurrence reports and is provided for information and guidance only. The data herein is dynamic and is therefore subject to change due to updated information. For the purpose of subsection 49(2) of the Transport Safety Investigation Act 2003 (TSI Act) any On-Board Recordings (OBR) relating to a matter the ATSB has decided not to investigate, as identified in this publication, are not to be treated as an OBR on and after the date of publication of this Weekly Summary. Section 48 of the Act contains a definition for an OBR. Part 6 Division 1 of the TSI Act provides for certain confidentiality protections which must be applied to OBRs.



Occurrences Entered into the ATSB Aviation Safety Database  
Between 10 December 2011 and 16 December 2011

Occurrence Date	ATSB Reference Number	Occurrence Category	ATSB Investigation	Location	State	Aircraft Manufacturer	Aircraft Model	Operation Type	Operation Sub Type	Airspace Type	Airspace Class	ATSB Summary
7/12/11	201108494	Incident	No	Emerald Aerodrome	QLD	BOMBARDIER INC	DHC-8-315	Air Transport High Capacity	Passenger	CTAF	G	During the landing roll, the aircraft struck a bird.
7/12/11	201108499	Incident	No	Maningrida Aerodrome	NT							The Maningrida VHF failed.
7/12/11	201108501	Incident	No	near Sunshine Coast Aerodrome	QLD	ROBINSON HELICOPTER CO	R44	General Aviation-Unknown	Unknown	CTR	D	The pilot did not report clear of controlled airspace and ATC could not establish communication with the pilot.
7/12/11	201108516	Incident	No	overhead Longreach Aerodrome	QLD	THE BOEING COMPANY	737-838	Air Transport High Capacity	Passenger	CTA	A	During the cruise, the pressurisation auto fail light illuminated and pressurisation was controlled in the alternate mode. The aircraft was returned to Brisbane. Engineers reset the pressurisation auto system and the fault cleared.
7/12/11	201108517	Serious Incident	No	Rottnest Island Aerodrome	WA	BEECH AIRCRAFT CORP	76	Flying Training	Training Dual	CTAF	G	During the approach, the pilot of the Beechcraft 58 took evasive action to avoid the Beechcraft 76 on a reciprocal track. The crew of the Beechcraft 76 were communicating with ATC on the area frequency at the time of the conflict.
						BEECH AIRCRAFT CORP	58	Aerial Work	Other			
8/12/11	201108484	Incident	No	IBABI (IFR)	NSW	THE BOEING COMPANY	747-438	Air Transport High Capacity	Passenger	CTA	A	During the cruise, the aircraft encountered moderate turbulence and the stick shaker activated twice.
8/12/11	201108488	Incident	No	PIBED (IFR), 335° M 9Km	Other	THE BOEING COMPANY	747-4H6	Air Transport High Capacity	Passenger	OCA	A	During the cruise, the aircraft diverted off track without a clearance.
8/12/11	201108491	Incident	No	Wagga Wagga Aerodrome	NSW	PIPER AIRCRAFT CORP	PA-28-161	Flying Training	Training Solo	CTAF	G	After landing, the left main landing gear tyre deflated.
8/12/11	201108496	Incident	No	Canberra Aerodrome	ACT	Unknown	Unknown	Military	Other	CTR	C	Incorrect coordination details were passed on a departing aircraft.
8/12/11	201108502	Incident	No	Hamilton Island Aerodrome, 060° M 11Km	QLD	DE HAVILLAND CANADA	DHC-2 MK 1 (U-6A)	General Aviation-Unknown	Unknown	CTR	D	The aircraft entered controlled airspace without a clearance.
8/12/11	201108503	Incident	No	overhead Griffith Aerodrome	NSW	Unknown	Unknown	Air Transport High Capacity	Passenger	CTA	A	During the cruise, the cabin crew detected fumes in the rear galley which spread throughout the cabin. An engineering inspection revealed the source of the fumes to be a recirculating fan.
8/12/11	201108504	Incident	No	Perth Aerodrome	WA	THE BOEING COMPANY	737-8FE	Air Transport High Capacity	Passenger	CTR	C	During the daily inspection, evidence of a bird strike was found. It could not be determined when the strike occurred.
8/12/11	201108505	Incident	No	Sydney Aerodrome	NSW	THE BOEING COMPANY	767-338	Air Transport High Capacity	Passenger	CTR	C	During loading of the aircraft, undeclared dangerous goods (CO2 bottles) were detected.
8/12/11	201108506	Incident	No	Clermont Aerodrome, 134° M 28Km	QLD	CESSNA AIRCRAFT COMPANY	525A	Charter	Unknown	CTA	E	The aircraft climbed into controlled airspace without a clearance.
8/12/11	201108509	Incident	No	Perth Aerodrome	WA	FOKKER B.V.	F28 MK 0100	Air Transport High Capacity	Passenger	CTR	C	During the approach, the aircraft struck a bird.
8/12/11	201108510	Incident	No	Dubbo Aerodrome	NSW	PIPER AIRCRAFT CORP	PA-31-350	Charter	Unknown	CTAF	G	During the initial climb, the aircraft struck a galah and returned to Dubbo.
8/12/11	201108512	Incident	No	Goulburn Aerodrome	NSW	CESSNA AIRCRAFT COMPANY	441	Private	Pleasure / Travel	CTAF	G	During the landing the pilot applied heavy braking and the right main tyre burst, damaging the rim and brake pads.

NOTE: This document is based on unverified occurrence reports and is provided for information and guidance only. The data herein is dynamic and is therefore subject to change due to updated information. For the purpose of subsection 49(2) of the Transport Safety Investigation Act 2003 (TSI Act) any On-Board Recordings (OBR) relating to a matter the ATSB has decided not to investigate, as identified in this publication, are not to be treated as an OBR on and after the date of publication of this Weekly Summary. Section 48 of the Act contains a definition for an OBR. Part 6 Division 1 of the TSI Act provides for certain confidentiality protections which must be applied to OBRs.



Occurrences Entered into the ATSB Aviation Safety Database  
Between 10 December 2011 and 16 December 2011

Occurrence Date	ATSB Reference Number	Occurrence Category	ATSB Investigation	Location	State	Aircraft Manufacturer	Aircraft Model	Operation Type	Operation Sub Type	Airspace Type	Airspace Class	ATSB Summary
8/12/11	201108520	Incident	No	EGATU (IFR), 174° M 99Km	Other	AIRBUS INDUSTRIE	A320-216	Air Transport High Capacity	Passenger	OCA	A	Coordination details were passed late on an aircraft approaching the airspace boundary.
8/12/11	201108521	Incident	No	Mangalore Aerodrome, 240° M 19Km	VIC	BEECH AIRCRAFT CORP	F33A	General Aviation-Unknown	Unknown	PRD	PRD	The aircraft entered restricted airspace without a clearance.
8/12/11	201108522	Incident	No	overhead Gold Coast Aerodrome	QLD	THE BOEING COMPANY	767-338	Air Transport High Capacity	Passenger	CTA	A	The aircraft departed the holding pattern early without a clearance.
8/12/11	201108525	Incident	No	near Hong Kong International Airport	Other	AIRBUS INDUSTRIE	A330-303	Air Transport High Capacity	Passenger	Other	Foreign	During the climb, the crew heard a large bang. An engineering inspection revealed that the forward cargo door was not correctly seated. The eccentric bushings were found to be worn.
8/12/11	201108528	Incident	No	Perth Aerodrome	WA	FAIRCHILD INDUSTRIES INC	SA227-DC	Air Transport Low Capacity	Passenger	CTR	C	During the landing roll, the aircraft struck a kestrel.
8/12/11	201108531	Incident	No	Perth Aerodrome	WA	THE BOEING COMPANY	747-438	Air Transport High Capacity	Passenger	CTR	C	During the landing roll, the aircraft struck a bird.
8/12/11	201108535	Incident	No	Sydney Aerodrome	NSW	AIRBUS INDUSTRIE	A320-232	Air Transport High Capacity	Passenger	CTR	C	The actual gross weight was different to the calculated gross weight.
8/12/11	201108540	Incident	No	Jandakot Aerodrome	WA	Unknown	Unknown	Unknown	Unknown	CTR	D	An open microphone inhibited ATC communications for a short period.
8/12/11	201108548	Incident	No	Sydney Aerodrome	NSW	THE BOEING COMPANY	737-838	Air Transport High Capacity	Passenger	CTR	C	Prior to departure, the captain's cockpit instruments failed. Engineers replaced the left air data inertial reference unit (ADIRU).
9/12/11	201108417	Incident	No	near Melbourne Aerodrome	VIC	AIRBUS INDUSTRIE	A320-232	Air Transport High Capacity	Passenger	CTR	C	During the approach, the aircraft struck a bird.
9/12/11	201108434	Incident	No	Narrabri Aerodrome	NSW	FAIRCHILD INDUSTRIES INC	SA227-AC	Air Transport Low Capacity	Freight	CTAF	G	During the landing, the aircraft struck a galah.
9/12/11	201108462	Incident	Yes	Sydney Aerodrome, 250° M 9Km	NSW	DE HAVILLAND CANADA S.O.C.A.T.A.-GROUPE AEROSPATIALE	DHC-8-201 TBM 700	Air Transport Low Capacity General Aviation-Unknown	Passenger Unknown	CTR	C	During the initial climb from Bankstown, the Aerospatiale TBM700 maintained runway heading which resulted in a breakdown of separation with a de Havilland Canada DHC-8 on final for runway 07 at Sydney. The investigation is continuing.
9/12/11	201108485	Incident	No	Melbourne Aerodrome	VIC	THE BOEING COMPANY	737-8FE	Air Transport High Capacity	Passenger	CTR	C	During the takeoff run, the aircraft ingested a crow into the right engine. The takeoff was rejected.
9/12/11	201108507	Incident	No	Bankstown Aerodrome	NSW	CESSNA AIRCRAFT COMPANY	152	General Aviation-Unknown	Unknown	CTR	D	The aircraft was cleared for a touch-and-go landing on runway 29L but subsequently conducted the landing on runway 29C.
9/12/11	201108508	Incident	No	near Mackay Aerodrome	QLD	CESSNA AIRCRAFT COMPANY	182Q	General Aviation-Unknown	Unknown	CTA	D	The aircraft climbed above its assigned level.
9/12/11	201108511	Incident	No	Grafton Aerodrome, 360° M 13Km	NSW	Unknown	Unknown	General Aviation-Unknown	Unknown	PRD	PRD	An aircraft entered restricted airspace without a clearance.
9/12/11	201108513	Incident	No	near Murray Bridge (ALA)	SA	PIPER AIRCRAFT CORP	PA-32R-300	Charter	Unknown	PRD	PRD	The aircraft entered restricted airspace without a clearance.

NOTE: This document is based on unverified occurrence reports and is provided for information and guidance only. The data herein is dynamic and is therefore subject to change due to updated information. For the purpose of subsection 49(2) of the Transport Safety Investigation Act 2003 (TSI Act) any On-Board Recordings (OBR) relating to a matter the ATSB has decided not to investigate, as identified in this publication, are not to be treated as an OBR on and after the date of publication of this Weekly Summary. Section 48 of the Act contains a definition for an OBR. Part 6 Division 1 of the TSI Act provides for certain confidentiality protections which must be applied to OBRs.



Occurrences Entered into the ATSB Aviation Safety Database  
Between 10 December 2011 and 16 December 2011

Occurrence Date	ATSB Reference Number	Occurrence Category	ATSB Investigation	Location	State	Aircraft Manufacturer	Aircraft Model	Operation Type	Operation Sub Type	Airspace Type	Airspace Class	ATSB Summary
9/12/11	201108514	Incident	No	Moorabbin Aerodrome	VIC	PIPER AIRCRAFT CORP	PA-46-500TP	Unknown	Unknown	CTR	D	The crew did not taxi in accordance with ATC instructions and the aircraft entered a runway without a clearance.
9/12/11	201108515	Incident	No	near Sydney Aerodrome	NSW	Airbus Industrie	A340-642X	Air Transport High Capacity	Passenger	CTA	C	The aircraft did not adhere to the tracking requirements of the KAMPI1 SID.
9/12/11	201108518	Incident	No	SASRO (IFR)	Other	AIRBUS INDUSTRIE	A320-232	Air Transport High Capacity	Passenger	CTA	A	During the cruise, the crew did not update a waypoint estimate with the aircraft arriving four minutes early.
9/12/11	201108526	Incident	No	Jandakot Aerodrome	WA	CESSNA AIRCRAFT COMPANY	177RG	Flying Training	Check & Training	CTR	D	During the initial climb, the crew noted abnormal engine and fuel flow indications and returned to Jandakot. While taxiing after landing, the engine stopped. The engineering inspection revealed two blocked fuel injectors.
9/12/11	201108527	Incident	No	Sydney Aerodrome	NSW	JETSTREAM AIRCRAFT LTD	3206	Air Transport Low Capacity	Passenger	CTR	C	During the landing, the aircraft struck a small bird.
9/12/11	201108529	Incident	No	near Sydney Aerodrome	NSW	THE BOEING COMPANY	737-8FE	Air Transport High Capacity	Passenger	CTR	C	During the takeoff, the crew detected fumes in both the flight deck and the cabin. The fumes dissipated early in the climb. Engineering could not find any fault, but suspect in may have been due to the lubricant used during a boroscope inspection.
9/12/11	201108534	Incident	No	Port Macquarie Aerodrome	NSW	Unknown	Unknown	Unknown	Unknown	CTAF	G	Whilst the ATR 72 was on downwind, an aircraft crossed tracks below and behind it. No radio calls had been heard from the other aircraft.
9/12/11	201108536	Incident	No	Brisbane Aerodrome	QLD	AIRBUS INDUSTRIE	A330-303	Air Transport High Capacity	Passenger		Unknown	During a post-flight inspection, The left number four inboard flap track inspection cover was found to be missing. It could not be determined when the cover had detached.
9/12/11	201108542	Incident	No	Melbourne Aerodrome, 240° M 56Km	VIC	Unknown	Unknown	Gliding	Unknown	OCTA	G	During the approach, the pilot of the Piper PA31 sighted a glider on a reciprocal track. The pilot of the PA31 manoeuvred to ensure separation.
9/12/11	201108543	Incident	No	Numbulwar Aerodrome, W M 46Km	NT	CESSNA AIRCRAFT COMPANY	404	Charter	Passenger	OCTA	G	During climb, the crew received a door warning and the top section of the door opened. The door was closed by a passenger and the flight continued. Engineers found that an over centre spring in the latching mechanism had failed.
9/12/11	201108545	Incident	No	near Brisbane Aerodrome	QLD	DE HAVILLAND CANADA	DHC-8-202	Air Transport High Capacity	Passenger	CTA	C	During climb, the crew received a right engine temperature warning and returned to Brisbane. Engineers replaced two thermocouples
9/12/11	201108547	Incident	No	near Melbourne Aerodrome	VIC	EMBRAER-EMPRESA BRASILEIRA DE AERONAUTICA	ERJ 190-100 IGW	Air Transport High Capacity	Passenger	CTA	C	During cruise, the aircraft was struck by lightning.
9/12/11	201108554	Serious Incident	No	Borroloola (ALA), SE M 56Km	NT	GIPPSLAND AERONAUTICS PTY LTD	GA-8	Aerial Work	Test & Ferry	OCTA	G	During the cruise, the engine failed. The pilot switched on the electric fuel pump and engine power was restored. The engineering inspection revealed a faulty engine driven fuel pump.
10/12/11	201108519	Incident	No	Sydney Aerodrome, 060° M 7Km	NSW	CESSNA AIRCRAFT COMPANY	152	General Aviation-Unknown	Unknown	CTR	C	The aircraft entered controlled airspace without a clearance.
10/12/11	201108530	Incident	No	Lancelin Township (VFR)	WA	PIPER AIRCRAFT CORP	PA-32R-301	General Aviation-Unknown	Unknown	PRD	PRD	The aircraft entered restricted airspace without a clearance.

NOTE: This document is based on unverified occurrence reports and is provided for information and guidance only. The data herein is dynamic and is therefore subject to change due to updated information. For the purpose of subsection 49(2) of the Transport Safety Investigation Act 2003 (TSI Act) any On-Board Recordings (OBR) relating to a matter the ATSB has decided not to investigate, as identified in this publication, are not to be treated as an OBR on and after the date of publication of this Weekly Summary. Section 48 of the Act contains a definition for an OBR. Part 6 Division 1 of the TSI Act provides for certain confidentiality protections which must be applied to OBRs.



Occurrences Entered into the ATSB Aviation Safety Database  
Between 10 December 2011 and 16 December 2011

Occurrence Date	ATSB Reference Number	Occurrence Category	ATSB Investigation	Location	State	Aircraft Manufacturer	Aircraft Model	Operation Type	Operation Sub Type	Airspace Type	Airspace Class	ATSB Summary
10/12/11	201108532	Incident	No	Perth Aerodrome	WA	EMBRAER-EMPRESA BRASILEIRA DE AERONAUTICA	ERJ 190-100 IGW	Air Transport High Capacity	Passenger	CTR	C	During the takeoff, the aircraft struck a bird.
10/12/11	201108533	Incident	No	Bankstown Aerodrome, W M 22Km	NSW	PIPER AIRCRAFT CORP	PA-28-161	Flying Training	Training Dual	OCTA	G	During the cruise, the engine misfired then returned to normal operation. The pilot subsequently detected fumes in the cockpit and the vacuum instruments failed. An engineering inspection revealed a faulty vacuum pump.
10/12/11	201108537	Incident	No	near Cairns Aerodrome	QLD	CESSNA AIRCRAFT COMPANY	404	General Aviation-Unknown	Unknown	CTA	C	The aircraft climbed above its assigned level.
10/12/11	201108541	Incident	No	Darwin Aerodrome, S M 19Km	NT	CESSNA AIRCRAFT COMPANY	210M	Charter	Unknown	CTA	C	During the climb, the pilot received an abnormal engine indication and returned to Darwin. Engineers replaced a faulty magneto.
10/12/11	201108544	Incident	No	Jandakot Aerodrome	WA	GIPPSLAND AERONAUTICS PTY LTD	GA-8	Charter	Unknown	CTR	D	The aircraft entered the taxiway without a clearance.
10/12/11	201108546	Incident	No	WEENA (IFR)	Other	CONVAIR	340	Air Transport Low Capacity	Freight	OCTA	G	Coordination details were passed late on an aircraft approaching the airspace boundary.
10/12/11	201108549	Incident	No	Lismore Aerodrome	NSW	S.A.A.B. AIRCRAFT CO	340B	Air Transport Low Capacity	Passenger	CTAF	G	During the landing roll, the aircraft struck two plovers.
10/12/11	201108550	Incident	No	Lismore Aerodrome	NSW	Unknown	Unknown	Unknown	Unknown	CTAF	G	The safety officer retrieved a duck carcass from the runway.
10/12/11	201108551	Incident	No	near Yeppoon (ALA)	QLD	CESSNA AIRCRAFT COMPANY	414A	Charter	Passenger	CTA	E	During the cruise, the aircraft was struck by lightning.
10/12/11	201108552	Incident	No	ONOXIA (IFR)	Other	AIRBUS INDUSTRIE	A321-231	Air Transport High Capacity	Passenger	OCA	A	No coordination details were passed on an aircraft approaching the airspace boundary.
10/12/11	201108555	Incident	No	Cairns Aerodrome	QLD	AIRBUS INDUSTRIE	A321-231	Air Transport High Capacity	Passenger	CTR	C	During a post-flight maintenance inspection, evidence of a birdstrike was found. It could not be determined when the strike occurred.
10/12/11	201108556	Incident	No	Canberra Aerodrome	ACT	ATR - GIE Avions de Transport Regional	ATR72-212A	Air Transport High Capacity	Passenger	CTR	C	During the take-off run, the aircraft struck a bird.
10/12/11	201108564	Accident	No	Cobar Aerodrome	NSW	Unknown	Unknown	Unknown	Unknown	CTAF	G	During the landing, the aircraft was struck by a gust of wind and rolled on its side. The aircraft sustained serious damage.
10/12/11	201108590	Incident	No	Wagga Wagga Aerodrome, 050° M 11Km	NSW	BOMBARDIER INC	DHC-8-402	Air Transport High Capacity	Passenger	CTAF	G	During the approach, the crew inadvertently lifted the flight idle gate locks and received a flight idle gate warning.
11/12/11	201108402	Incident	No	Sydney Aerodrome	NSW							The safety officer retrieved a Richard's pipit carcass from the runway.
11/12/11	201108405	Incident	No	Sydney Aerodrome	NSW	THE BOEING COMPANY	737-838	Air Transport High Capacity	Passenger	CTR	C	During the landing roll, an aircraft struck a black shouldered kite.
11/12/11	201108415	Incident	No	near Melbourne Aerodrome	VIC	BOMBARDIER INC	DHC-8-315	Air Transport High Capacity	Passenger	CTR	C	During the initial climb, several flight instruments failed and the aircraft was returned to Melbourne. Engineers replaced the left attitude and heading reference system.
11/12/11	201108418	Accident	No	Moree Aerodrome, 100° M 33Km	NSW	AIR TRACTOR INC	AT-502B	Aerial Work	Aerial Agriculture	OCTA	G	While conducting aerial spraying, the aircraft struck a powerline and conducted a precautionary landing at Moree. The aircraft's tail was substantially damaged.

NOTE: This document is based on unverified occurrence reports and is provided for information and guidance only. The data herein is dynamic and is therefore subject to change due to updated information. For the purpose of subsection 49(2) of the Transport Safety Investigation Act 2003 (TSI Act) any On-Board Recordings (OBR) relating to a matter the ATSB has decided not to investigate, as identified in this publication, are not to be treated as an OBR on and after the date of publication of this Weekly Summary. Section 48 of the Act contains a definition for an OBR. Part 6 Division 1 of the TSI Act provides for certain confidentiality protections which must be applied to OBRs.



Occurrences Entered into the ATSB Aviation Safety Database  
Between 10 December 2011 and 16 December 2011

Occurrence Date	ATSB Reference Number	Occurrence Category	ATSB Investigation	Location	State	Aircraft Manufacturer	Aircraft Model	Operation Type	Operation Sub Type	Airspace Type	Airspace Class	ATSB Summary
11/12/11	201108425	Incident	No	Melbourne Aerodrome	VIC	BOMBARDIER INC	DHC-8-402	Air Transport High Capacity	Passenger	CTR	C	During the initial climb, the aircraft struck a bird.
11/12/11	201108428	Incident	No	Sydney Aerodrome, 350° M 130Km	NSW	BOMBARDIER INC	DHC-8-315	Air Transport High Capacity	Passenger	CTA	C	During the holding pattern, the aircraft was struck by lightning.
11/12/11	201108440	Incident	No	KETEN (IFR)	QLD	BOMBARDIER INC	DHC-8-402	Air Transport High Capacity	Passenger	CTA	E	During the cruise, the aircraft was struck by lightning.
11/12/11	201108538	Incident	No	Albury Aerodrome	NSW	SKYFOX AVIATION LTD	GAZELLE	General Aviation-Unknown	Unknown	CTR	D	The aircraft entered controlled airspace without a clearance. The pilot was transmitting on an incorrect frequency.
11/12/11	201108539	Incident	No	Broome Aerodrome	WA	THE BOEING COMPANY	717-200	Air Transport High Capacity	Passenger	CTR	D	The aircraft did not taxi in accordance with a NOTAM.
11/12/11	201108558	Incident	No	AMANA (IFR)	WA	CESSNA AIRCRAFT COMPANY	550	General Aviation-Unknown	Unknown	CTA	A	During the cruise, the aircraft diverted off track without a clearance.
11/12/11	201108559	Incident	No	Gold Coast Aerodrome, 350° M 13Km	QLD	AMATEUR BUILT AIRCRAFT	EUROPA	General Aviation-Unknown	Unknown	CTR	C	The pilot did not comply with an ATC instruction to remain outside controlled airspace and the aircraft entered controlled airspace without a clearance.
11/12/11	201108560	Incident	No	Rockhampton Aerodrome, 270° M 28Km	QLD	BELL HELICOPTER CO	206B	General Aviation-Unknown	Unknown	CTA	D	The aircraft entered controlled airspace without a clearance.
11/12/11	201108561	Incident	No	Jandakot Aerodrome	WA	BEECH AIRCRAFT CORP	A36	Private	Unknown	CTR	D	During the landing roll, the right main landing gear tyre burst.
11/12/11	201108562	Incident	No	Mount Isa Aerodrome	QLD	THE BOEING COMPANY	737-838	Air Transport High Capacity	Passenger	CTAF	G	During the landing roll, the aircraft struck two Australian coursers.
11/12/11	201108563	Incident	No	Brisbane Aerodrome	QLD	THE BOEING COMPANY	737-838	Air Transport High Capacity	Passenger	CTR	C	The taxiway and runway lights partially failed and the precision approach path indicator (PAPI) lights completely failed for 53 minutes
11/12/11	201108565	Incident	No	VEPAS (IFR)	Other	THE BOEING COMPANY	737-8FE	Air Transport High Capacity	Passenger	OCA	A	During the cruise, the crew did not update a waypoint estimate with the aircraft arriving six minutes early.
11/12/11	201108566	Incident	No	Darwin Aerodrome	NT	CESSNA AIRCRAFT COMPANY	210M	Charter	Passenger	CTR	C	During the landing roll, the right landing gear tyre deflated.
11/12/11	201108567	Incident	No	Mount Isa Aerodrome	QLD	Hawker Beechcraft Corporation	B200C	Aerial Work	EMS	CTAF	G	During the takeoff, the aircraft struck a bird.
11/12/11	201108568	Incident	No	Cairns Aerodrome	QLD	THE BOEING COMPANY	737-838	Air Transport High Capacity	Passenger	CTR	C	During the landing, the aircraft struck a bird.
11/12/11	201108570	Incident	No	Sydney Aerodrome	NSW							The taxiway was closed due to flooding.
11/12/11	201108571	Incident	No	near Sydney Aerodrome	NSW	BOMBARDIER INC	DHC-8-402	Air Transport High Capacity	Passenger	CTA	C	During the climb, the aircraft was struck by lightning and returned to Sydney.
11/12/11	201108576	Incident	No	WELSH (IFR)	NSW	BOMBARDIER INC	DHC-8-402	Air Transport High Capacity	Passenger	CTA	C	During the descent, the crew received a de-ice pressure warning and actioned the non-normal checklist. An engineering inspection found a large number of splits in the de-ice boots.

NOTE: This document is based on unverified occurrence reports and is provided for information and guidance only. The data herein is dynamic and is therefore subject to change due to updated information. For the purpose of subsection 49(2) of the Transport Safety Investigation Act 2003 (TSI Act) any On-Board Recordings (OBR) relating to a matter the ATSB has decided not to investigate, as identified in this publication, are not to be treated as an OBR on and after the date of publication of this Weekly Summary. Section 48 of the Act contains a definition for an OBR. Part 6 Division 1 of the TSI Act provides for certain confidentiality protections which must be applied to OBRs.



Occurrences Entered into the ATSB Aviation Safety Database  
Between 10 December 2011 and 16 December 2011

Occurrence Date	ATSB Reference Number	Occurrence Category	ATSB Investigation	Location	State	Aircraft Manufacturer	Aircraft Model	Operation Type	Operation Sub Type	Airspace Type	Airspace Class	ATSB Summary
11/12/11	201108577	Incident	No	Brisbane Aerodrome	QLD	DE HAVILLAND CANADA	DHC-8-202	Air Transport Low Capacity	Passenger	CTR	C	During taxi, the windshield cracked.
11/12/11	201108582	Incident	No	Calga (NDB)	NSW	BOMBARDIER INC	DHC-8-315	Air Transport High Capacity	Passenger	CTA	C	During the descent, the aircraft was struck by lightning.
11/12/11	201108584	Incident	No	Suvarnabhumi Airport (Bangkok)	Other	THE BOEING COMPANY	747-438	Air Transport High Capacity	Passenger	Other	Foreign	During approach, the crew inadvertently selected takeoff/go around (TOGA) and subsequently deselected the autothrottle. The aircraft speed reduced below the reference speed before the crew disconnected the autopilot and continued the approach.
11/12/11	201108589	Accident	No	Port Macquarie Aerodrome, NW M 16Km	NSW	Van's Aircraft	RV-12	Sports Aviation	Other	OCTA	G	The aircraft landed hard, resulting in the nose landing gear detaching. The aircraft was seriously damaged.
11/12/11	201108592	Incident	No	Perth Aerodrome	WA	Unknown	Unknown	Air Transport High Capacity	Passenger	CTR	C	During the unloading, undeclared dangerous goods (oxygen bottle) were detected.
12/12/11	201108431	Incident	No	Moruya Aerodrome, 360° M 46Km	NSW	S.A.A.B. AIRCRAFT CO	340B	Air Transport Low Capacity	Passenger	OCTA	G	The aircraft descended below its assigned level.
12/12/11	201108454	Incident	No	Griffith Aerodrome	NSW	S.A.A.B. AIRCRAFT CO	340B	Air Transport Low Capacity	Passenger	CTAF	G	During the takeoff, the aircraft struck a galah.
12/12/11	201108569	Incident	No	Rockhampton Aerodrome, 305° M 11Km	QLD	BELL HELICOPTER CO	206B (III)	Aerial Work	Survey / Photographic	CTR	D	The aircraft entered controlled airspace without a clearance.
12/12/11	201108573	Incident	No	Lord Howe Island Aerodrome	NSW							The Lord Howe ADS-B failed.
12/12/11	201108574	Incident	No	Moorabbin Aerodrome, N M 4Km	VIC	PIPER AIRCRAFT CORP	PA-28-161	General Aviation-Unknown	Unknown	CTR	D	On departure, the aircraft turned off track without a clearance and the pilot was not able to be contacted.
12/12/11	201108579	Incident	No	Kingscote Aerodrome, 360° M 2Km	QLD	Unknown	Unknown	General Aviation-Unknown	Unknown	PRD	PRD	An aircraft entered restricted airspace without a clearance.
12/12/11	201108580	Incident	No	near Adelaide Aerodrome	SA	THE BOEING COMPANY	737-476	Air Transport High Capacity	Passenger	CTR	C	During the approach, the aircraft struck a bird.
12/12/11	201108581	Incident	No	Bankstown Aerodrome, 111° M 9Km	NSW	BRITISH AEROSPACE PLC	3202	General Aviation-Unknown	Unknown	CTR	C	The aircraft did not adhere to the altitude or tracking requirements of the BANKSTOWN SIX DEPARTURE, and entered controlled airspace without a clearance.
12/12/11	201108583	Incident	No	VICTA (IFR), 355° M 222Km	QLD	THE BOEING COMPANY	737-838	Air Transport High Capacity	Passenger	CTA	A	During cruise, the navigation screens failed and the aircraft diverted to Brisbane. The engineering inspection found no faults with the system.
12/12/11	201108585	Incident	No	Parafield Aerodrome	SA	PIPER AIRCRAFT CORP	PA-28-181	General Aviation-Unknown	Unknown	CTR	D	The aircraft was cleared to land on runway 21R but was observed on final for runway 26R. ATC instructed the crew to make a missed approach. The aircraft made another approach to runway 26R after being instructed to use runway 21R. ATC subsequently cleared the aircraft to land on runway 26R.
12/12/11	201108586	Incident	No	KANGA (IFR)	NSW	PIPER AIRCRAFT CORP	PA-31-350	Charter	Unknown	OCTA	G	During the cruise, the crew did not update a waypoint estimate, with the aircraft arriving five minutes early.

NOTE: This document is based on unverified occurrence reports and is provided for information and guidance only. The data herein is dynamic and is therefore subject to change due to updated information. For the purpose of subsection 49(2) of the Transport Safety Investigation Act 2003 (TSI Act) any On-Board Recordings (OBR) relating to a matter the ATSB has decided not to investigate, as identified in this publication, are not to be treated as an OBR on and after the date of publication of this Weekly Summary. Section 48 of the Act contains a definition for an OBR. Part 6 Division 1 of the TSI Act provides for certain confidentiality protections which must be applied to OBRs.



Occurrences Entered into the ATSB Aviation Safety Database  
Between 10 December 2011 and 16 December 2011

Occurrence Date	ATSB Reference Number	Occurrence Category	ATSB Investigation	Location	State	Aircraft Manufacturer	Aircraft Model	Operation Type	Operation Sub Type	Airspace Type	Airspace Class	ATSB Summary
12/12/11	201108588	Incident	No	near AVKAN (IFR)	WA	EMBRAER-EMPRESA BRASILEIRA DE AERONAUTICA	EMB-120 ER	Charter	Passenger	OCTA	G	During cruise, the aircraft encountered severe turbulence.
12/12/11	201108593	Incident	No	Evans Head (ALA), 360° M 19Km	NSW	Boeing	F/A 18-E	Military	Other	CTA	C	The aircraft entered controlled airspace without a clearance.
12/12/11	201108594	Incident	No	Mount Isa Aerodrome	QLD	BEECH AIRCRAFT CORP	B200	Charter	Passenger	CTAF	G	During the post flight inspection, evidence of a bird strike was found. It could not be determined when the strike occurred.
12/12/11	201108595	Incident	No	Brisbane Aerodrome	QLD	EMBRAER-EMPRESA BRASILEIRA DE AERONAUTICA	ERJ 190-100 IGW	Air Transport High Capacity	Passenger	CTR	C	During the approach, the aircraft encountered overshoot windshear
12/12/11	201108596	Incident	No	HENDO (IFR), 270° M 9Km	QLD	BEECH AIRCRAFT CORP	58	General Aviation-Unknown	Unknown	CTA	C	The aircraft did not adhere to the tracking requirements of the RWY 33 HENDO FIVE ALPHA STAR.
12/12/11	201108597	Incident	No	Adelaide Aerodrome, 042° M 20Km	SA	AERO COMMANDER	500-S	Charter	Freight	CTA	C	During the approach, the aircraft diverted off track without a clearance.
12/12/11	201108598	Incident	No	ENTAL (IFR)	WA	FOKKER B.V.	F28 MK 0100	Air Transport High Capacity	Passenger	CTAF	G	During the climb, the cabin crew heard a loud bang from the galley and observed fumes and a grey haze. An inspection revealed a faulty coffee machine.
12/12/11	201108602	Incident	No	Adelaide Aerodrome	SA	THE BOEING COMPANY	737-476	Air Transport High Capacity	Passenger	CTR	C	During unloading, unmanifested dangerous goods (petrol driven chainsaws) were detected.
12/12/11	201108605	Incident	No	Mount Isa Aerodrome, 342° M 3Km	QLD	CESSNA AIRCRAFT COMPANY	208	Business	Unknown	CTAF	G	During final approach, the aircraft struck a fruit bat.
13/12/11	201108587	Incident	No	Brisbane Aerodrome	QLD	THE BOEING COMPANY	737-8FE	Air Transport High Capacity	Passenger	CTR	C	During the landing, the aircraft struck a bird.
13/12/11	201108606	Incident	No	Geraldton Aerodrome	WA	BOMBARDIER INC	DHC-8-402	Air Transport High Capacity	Passenger	CTAF	G	During the landing roll, the aircraft struck a bird.
13/12/11	201108608	Incident	No	near Adelaide Aerodrome	SA	CESSNA AIRCRAFT COMPANY	182T	General Aviation-Unknown	Unknown	CTR	C	The aircraft climbed above the assigned level and was not in normal communication with ATC.
13/12/11	201108609	Incident	No	SULON (IFR), 011° M 13Km	Other	AIRBUS INDUSTRIE	A330-343X	Air Transport High Capacity	Passenger	Other	Foreign	During the cruise, the aircraft diverted off track without a clearance.
13/12/11	201108610	Incident	No	Mount Isa Aerodrome	QLD	DE HAVILLAND CANADA	DHC-8-102	Air Transport Low Capacity	Passenger	CTAF	G	During the landing roll, the aircraft struck a courser.
13/12/11	201108611	Incident	No	Kambalda (ALA), 220° M 278Km	WA	BOMBARDIER INC	DHC-8-315	Air Transport High Capacity	Passenger	CTA	E	No coordination details were passed on an aircraft approaching the airspace boundary.
13/12/11	201108616	Incident	No	Sydney Aerodrome	NSW	S.A.A.B. AIRCRAFT CO	340B	Air Transport Low Capacity	Passenger	CTR	C	During a post-flight inspection, evidence of a birdstrike was found on the left engine. It could not be determined when the strike occurred.
13/12/11	201108617	Incident	No	Hamilton Island Aerodrome	QLD							The Hamilton Island VHF transmitter and VOR failed due to a lightning strike. The runway lights failed briefly due to an associated power outage.

NOTE: This document is based on unverified occurrence reports and is provided for information and guidance only. The data herein is dynamic and is therefore subject to change due to updated information. For the purpose of subsection 49(2) of the Transport Safety Investigation Act 2003 (TSI Act) any On-Board Recordings (OBR) relating to a matter the ATSB has decided not to investigate, as identified in this publication, are not to be treated as an OBR on and after the date of publication of this Weekly Summary. Section 48 of the Act contains a definition for an OBR. Part 6 Division 1 of the TSI Act provides for certain confidentiality protections which must be applied to OBRs.



Occurrences Entered into the ATSB Aviation Safety Database  
Between 10 December 2011 and 16 December 2011

Occurrence Date	ATSB Reference Number	Occurrence Category	ATSB Investigation	Location	State	Aircraft Manufacturer	Aircraft Model	Operation Type	Operation Sub Type	Airspace Type	Airspace Class	ATSB Summary
13/12/11	201108618	Incident	No	Narrabri Aerodrome	NSW	JETSTREAM AIRCRAFT LTD	3206	Air Transport Low Capacity	Passenger	CTAF	G	During the landing roll, the aircraft struck a galah.
13/12/11	201108619	Incident	No	Mackay Aerodrome, 139° M 6Km	QLD	BOMBARDIER INC	DHC-8-315	Air Transport High Capacity	Passenger	CTR	D	During the approach, in moderate turbulence the stick shaker activated momentarily.
13/12/11	201108620	Incident	No	Sydney Aerodrome	NSW	BOMBARDIER INC	DHC-8-402	Air Transport High Capacity	Passenger	CTR	C	The aircraft did not adhere to the taxi clearance.
13/12/11	201108624	Incident	No	SAPDA (IFR)	Other	AIRBUS INDUSTRIE	A330-341	Air Transport High Capacity	Passenger	OCA	A	Incorrect coordination details were passed on an aircraft approaching the airspace boundary.
13/12/11	201108625	Incident	No	ELBIS (IFR), 045° M 65Km	Other	AIRBUS INDUSTRIE	A330-223	Air Transport High Capacity	Passenger	Other	Foreign	During the cruise, the aircraft diverted off track without a clearance.
13/12/11	201108626	Incident	No	Jandakot Aerodrome	WA	CESSNA AIRCRAFT COMPANY	172N	Flying Training	Training Dual	CTAF	G	The Cessna 172S began its takeoff run before the landing Cessna 172N was clear of the runway. The crew of the 172S rejected the takeoff after being informed by the 172N crew that they were not yet clear of the runway.
						CESSNA AIRCRAFT COMPANY	172S	Unknown	Unknown			
14/12/11	201108613	Incident	No	Brisbane Aerodrome	QLD	ATR - GIE Avions de Transport Regional	ATR72-212A	Air Transport Low Capacity	Passenger	CTR	C	The aircraft did not adhere to the taxi clearance.
14/12/11	201108614	Incident	No	Essendon Aerodrome, 077° M 5Km	VIC	VULCANAIR S.P.A.	P.68C	General Aviation-Unknown	Unknown	CTR	C	The aircraft turned onto an incorrect heading.
14/12/11	201108615	Incident	No	Bankstown Aerodrome	NSW	CIRRUS DESIGN CORPORATION	SR22	General Aviation-Unknown	Unknown	CTR	D	The aircraft was cleared to land on runway 29R but landed on runway 29C.
14/12/11	201108621	Incident	No	Perth Aerodrome	WA	THE BOEING COMPANY	737-838	Air Transport High Capacity	Passenger	CTR	C	During the landing roll, the aircraft struck a bird.
14/12/11	201108623	Incident	No	CULIN (IFR)	NSW	THE BOEING COMPANY	737-838	Air Transport High Capacity	Passenger	CTA	A	During the cruise, the aircraft diverted off track without a clearance.
14/12/11	201108627	Incident	No	FLIKI (IFR)	TAS	BOMBARDIER INC	DHC-8-402	Air Transport High Capacity	Passenger	CTA	C	The aircraft climbed above the assigned altitude.
14/12/11	201108629	Incident	No	Coffs Harbour Aerodrome, 203° M 50Km	NSW	PIPER AIRCRAFT CORP	PA-31-350	General Aviation-Unknown	Unknown	CTA	C	The aircraft descended below the assigned altitude.
14/12/11	201108630	Incident	No	TARAL (IFR)	NSW	THE BOEING COMPANY	737-8BK	Air Transport High Capacity	Passenger	CTA	A	The aircraft did not adhere to the direction of turn in the holding pattern.
14/12/11	201108631	Incident	No	Sydney Aerodrome	NSW	THE BOEING COMPANY	737-7Q8	Air Transport High Capacity	Passenger	CTR	C	During final approach, the aircraft struck a flying fox.
14/12/11	201108632	Incident	No	Adelaide Aerodrome	SA	PIPER AIRCRAFT CORP	PA-31-350	General Aviation-Unknown	Unknown	CTR	C	The crew did not comply with the taxi clearance.
14/12/11	201108633	Incident	No	Hamilton Island Aerodrome	QLD	THE BOEING COMPANY	737-82R	Air Transport High Capacity	Passenger	CTAF	G	During the initial climb, the aircraft struck a duck.

NOTE: This document is based on unverified occurrence reports and is provided for information and guidance only. The data herein is dynamic and is therefore subject to change due to updated information. For the purpose of subsection 49(2) of the Transport Safety Investigation Act 2003 (TSI Act) any On-Board Recordings (OBR) relating to a matter the ATSB has decided not to investigate, as identified in this publication, are not to be treated as an OBR on and after the date of publication of this Weekly Summary. Section 48 of the Act contains a definition for an OBR. Part 6 Division 1 of the TSI Act provides for certain confidentiality protections which must be applied to OBRs.



Occurrences Entered into the ATSB Aviation Safety Database  
Between 10 December 2011 and 16 December 2011

Occurrence Date	ATSB Reference Number	Occurrence Category	ATSB Investigation	Location	State	Aircraft Manufacturer	Aircraft Model	Operation Type	Operation Sub Type	Airspace Type	Airspace Class	ATSB Summary
14/12/11	201108634	Incident	No	Melbourne Aerodrome	VIC	THE BOEING COMPANY	767-338	Air Transport High Capacity	Passenger	CTR	C	During the landing roll, the aircraft struck a bird.
14/12/11	201108635	Incident	No	Wagga Wagga Aerodrome	NSW	PIPER AIRCRAFT CORP	PA-44-180	Flying Training	Training Solo	CTAF	G	During the landing, the aircraft struck a bird.
14/12/11	201108645	Incident	No	METUM (IFR)	Other	THE BOEING COMPANY	737-8FE	Air Transport High Capacity	Passenger	CTA	A	Coordination details were passed late on an aircraft approaching the airspace boundary.
14/12/11	201108646	Incident	No	ONOXIA (IFR)	Other	DASSAULT-AVIATION	FALCON 900	General Aviation-Unknown	Unknown	CTA	A	Incorrect coordination details were passed on an aircraft approaching the airspace boundary.
14/12/11	201108647	Incident	No	RIGMI (IFR)	Other	AIRBUS INDUSTRIE	A320-232	Air Transport High Capacity	Passenger	CTA	A	During the cruise, the crew did not update a waypoint estimate with the aircraft arriving five minutes early.
15/12/11	201108607	Accident	Yes	near Tyabb (ALA)	VIC	AUSTER AIRCRAFT LTD	J5F	General Aviation-Unknown	Unknown	CTAF	G	During the takeoff roll, the aircraft collided with an obstacle and came to rest inverted. The investigation is continuing.

NOTE: This document is based on unverified occurrence reports and is provided for information and guidance only. The data herein is dynamic and is therefore subject to change due to updated information. For the purpose of subsection 49(2) of the Transport Safety Investigation Act 2003 (TSI Act) any On-Board Recordings (OBR) relating to a matter the ATSB has decided not to investigate, as identified in this publication, are not to be treated as an OBR on and after the date of publication of this Weekly Summary. Section 48 of the Act contains a definition for an OBR. Part 6 Division 1 of the TSI Act provides for certain confidentiality protections which must be applied to OBRs.