

**Aviation Safety Investigation Report
199800051**

**Boeing Co
B747
Israel Aircraft Industries Ltd
Westwind**

06 January 1998

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at www.atsb.gov.au.

The operator of VH-AJJ reported that the flight test was to observe the operation of the aircraft's pressurisation system. The pilot was aware of the departing B747 from the parallel runway but was intent on cabin and engine instruments during the initial climb. He realised he had failed to comply with the SID when he was instructed to turn left.

