LOCATION OF OCCUPRENCE

## AIRCRAFT ACCIDENT INVESTIGATION SUMMARY REPORT

Reference No.

AS/	7	24	/1	035	
-----	---	----	----	-----	--

Andamooka, South Australia		Height a.m.s.l. (lt) 250 feet	Dote 29,12,72	Time (Local) 2025	Zone CSu7
THE AIRCRAFT		·····		<b>4</b>	
Cessna 172E Registration VH-DIT		Certificate of Airworthiness	Volid from Volid to 30.4.65 29.4.74		4
J.J. Organ,	Operator R.A. Wright,		Degree of damage to aircraft Destroyed		
62 South Circular Road,	Box 719F, G.P.O.,		Other property damaged		
Tullamarine, Victoria.	Melbourne, Victoria.		Shed		
Defects discovered					
		•			

Last or intended departure point	Time of departure	Next point of intended londing	Purpose of flight	Class of operation
Andamooka	2010	Point of departure	Local	Private

4,	THE	CREW

		· · · · · · · · · · · · · · · · · · ·				
Name	Status	Age	Class of licence	Hours on type	Total hours	Degree of injury
Raymond Albert WRIGHT	Pilot	26	Unlicenced	55	242	Fatal

## 5. OTHER PERSONS (All passengers and persons injured on ground)

Name	Stotus	Degree of injury	Name	Status	Degree of injury

## RELEVANT EVENTS

The pilot's Private Pilot Licence had expired on 31 October, 1972 and he had not made application for its renewal. He continued to fly after the lapse of his licence and on the morning of the day on which the accident occurred, he piloted VH-DIT from Adelaide to Andamooka, with three passengers. He had visited Andamooka on several previous occasions and at these times stayed with the family of his married sister, who lived within the environs of the town.

After their arrival the four occupants of the aircraft went to a restaurant at about 1330 hours, had a meal and began to consume alcoholic drinks. Drinking continued throughout the afternoon as other friends joined the party and the pilot was observed to drink a quantity of alcohol during this period. As evening approached the pilot made some remarks which suggested to others present that he intended to go flying. Efforts were made to dissuade him, but at approximately 1940 hours he left the group and hitch hiked to the aerodrome, situated some four miles north of the town. At the aerodrome he was seen to untie and board the aircraft, in which he then took off and flew towards the township at a low altitude.

Arriving over the town area at approximately 2020 hours, the pilot began a number of low runs, descending generally to roof top level except near the residence of his sister, where he flew just above the ground. While the pilot was flying past this house for the third time, the port wing dipped slightly and struck the corner of a shed adjacent to the main building. The aircraft then crashed to the ground and cartwheeled for a distance of 420 feet before coming to rest. Fire broke out immediately upon impact and destroyed the major portion of the wreckage.

## 7. OPINION AS TO CAUSE

The cause of the accident was that the pilot, whose judgement and ability were impaired by the consumption of alcohol, operated the aircraft at on unsafe altitude.

Report released	Designation	Date
C Flucham (D.S. GRAHAM)	Assistant Director-General (Air Safety Investigation)	11.5.73
		<u> </u>