Aviation Safety Investigation Report 198701444

Kavanagh K160 Balloon

20 September 1987

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the CEO of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the CEO of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at <u>www.atsb.gov.au</u>.

This accident was not the subject of an on-site investigation.						
Occurrence Number:		198701444			Occurrence Type: Accident	
Location:		4 km E Rutherglen VIC				
Date:		20 September 1987			Time: 915	
Highest Injury Level:		Serious				
Injuries:						
-			Fatal	Serious	Minor	None
		Crew	0	0	1	1
		Ground	0	0	0	-
		Passenger	0	1	3	4
		Total	0	1	3	5
Aircraft Details:	Kavana	igh K160 Ba	alloon			
Registration:	VH-HGU					
Serial Number:	KB047					
	Charter (Passenger					
Operation Type:	Operations)					
Damage Level:	Minor	,				
0	9 km W Rutherglen VIC					
Departure Time:						
Destination:	Rutherglen Racecourse VIC					
						

This accident was not the subject of an on-site investigation.

Approved for Release: March 14th 1988

Circumstances:

During the flight the groundspeed of the balloon increased to an estimated 12 knots, and the pilot decided to land in a showground. This area was surrounded by large trees. In the final stages of the landing attempt, the balloon was affected by a windshear and began to sink. The pilot activated the burners but the balloon struck a 15 metre high tree. Fearing that the balloon would overshoot the planned landing area, the pilot activated the rip panel. A heavy landing resulted and the basket rolled over in the direction of flight. One passenger was thrown from the basket and received a broken leg.