1

Aviation Safety Investigation Report 199000111

Maxair Drifter A-503

01 September 1990

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the CEO of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the CEO of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at www.atsb.gov.au.

This accident was not formally investigated by the Bureau.

Occurrence Number: 199000111 Occurrence Type: Accident

Location: 4km East of King Edward River Station WA (305km W Kununurra WA)

Date: 01 September 1990 **Time:** 745

Highest Injury Level: Serious

Injuries:

| | Fatal | Serious | Minor | None |
|-----------|-------|---------|-------|------|
| Crew | 0 | 1 | 0 | 0 |
| Ground | 0 | 0 | 0 | - |
| Passenger | 0 | 0 | 0 | 1 |
| Total | 0 | 1 | 0 | 1 |

Aircraft Details: Maxair Drifter A-503

Registration: AUF 25-0316
Serial Number: DR89-0372
Operation Type: Sport Aviation
Damage Level: Substantial
Departure Point: Muster Yard

Departure Time: N/A

Destination: King Edward River Station

WA

Approved for Release: 10th October 1990

Circumstances:

The pilot reported that the aircraft engine suffered a partial power loss as he was climbing out from a water hole inspection. Pumping the choke lever restored some power, however he was eventually forced to stall the aircraft into the tops of some tall trees. The aircraft fell approximately 30 feet to the ground with the pilot receiving back injuries during the fall.