Aviation Safety Investigation Report 198703532

Drifter XP 503

29 August 1987

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the CEO of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the CEO of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at www.atsb.gov.au.

Occurrence Number: 198703532 Occurrence Type: Accident

Location: Meriman Station (150 km SW Longreach) QLD **Date:** 29 August 1987 **Time:** 815

Highest Injury Level: Minor

Injuries:

	Fatal	Serious	Minor	None
Crew	0	0	1	1
Ground	0	0	0	-
Passenger	0	0	1	0
Total	0	0	1	1

Aircraft Details: Drifter XP 503 **Registration:** Not Registered

Serial Number: N/K

Operation Type: Sport Aviation **Damage Level:** Substantial

Departure Point: Meriman Station QLD

Departure Time: 0815

Destination: Meriman Station QLD

Approved for Release: September 24th 1987

Circumstances:

On arrival at the property, the pilot landed the aircraft in front of the homestead. A short time later he departed with the property owner on board for a cattle spotting flight. On returning to land, again in front of the homestead, the aircraft hit a single powerline, pitched nose up and fell to the ground inverted. The pilot stated that he was not aware of the presence of the powerline prior to colliding with it.