Aviation Safety Investigation Report 198502536

Cessna 182 RG

18 April 1985

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the CEO of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the CEO of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at www.atsb.gov.au.

Occurrence Number: 198502536 Occurrence Type: Accident

Location: Maitland NSW

Date: 18 April 1985 **Time:** 1055 (Aprx)

Highest Injury Level: Nil

Injuries:

	Fatal	Serious	Minor	None
Crew	0	0	1	1
Ground	0	0	0	-
Passenger	0	0	0	0
Total	0	0	0	1

Aircraft Details: Cessna 182 RG **Registration:** VH-SMV

Serial Number:

Operation Type: Test Flight
Damage Level: Substantial
Departure Point: Maitland NSW
Departure Time: 1055 (Aprx)
Destination: Maitland NSW

Approved for Release: 31st July, 1985

Circumstances:

The pilot decided to carry out a circuit in order to check the performance of the engine. Because of the presence of a gusting 20 knot westerly wind, a higher than normal approach speed was flown. The pilot stated that he closed the throttle at about 50 feet agl and flared the aircraft. The subsequent landing was heavy, the aircraft bounced, the pilot moved the control column forward and the aircraft bounced a second time. On the third touch down the pilot reported that the tail struck the runway causing substantial damage to the tail area of the aircraft.