## **Aviation Safety Investigation Report 198602312**

Cessna A185 F

**10 February 1986** 

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the CEO of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the CEO of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at www.atsb.gov.au.

Occurrence Number: 198602312 Occurrence Type: Accident

**Location:** Bannaby (16 km East Taralga) NSW

**Date:** 10 February 1986 **Time:** 810

**Highest Injury Level:** Nil

**Injuries:** 

	Fatal	Serious	Minor	None
Crew	0	0	1	1
Ground	0	0	0	-
Passenger	0	0	0	0
Total	0	0	0	1

**Aircraft Details:** Cessna A185 F **Registration:** VH-CWH

**Serial Number:** 

**Operation Type:** Aerial Work (Agricultural)

**Damage Level:** Substantial **Departure Point:** Gunning NSW

**Departure Time:** 0810

**Destination:** Bannaby NSW

**Approved for Release:** April 7th 1986

## **Circumstances:**

Prior to his DEPARTURE for the agricultural strip, the pilot had been assured that there would be no stock in the paddock containing the strip. As the aircraft was flared for landing, three sheep ran out from tall thistles adjacent to the strip. One of the sheep struck the right main gear leg and the pilot conducted a go around. He was informed that the leg was out of alignment, and elected to divert to a more suitable aerodrome. The gear leg folded during the landing run. The person who advised the pilot that there was no stock on the strip had not made a thorough inspection of the area.