## **Aviation Safety Investigation Report 198602315**

**Grob Astir CS** 

**15 February 1986** 

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the CEO of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the CEO of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at www.atsb.gov.au.

This accident was not subject to an on scene investigation.

Occurrence Number: 198602315 Occurrence Type: Accident

**Location:** Bunyan (16 km North Cooma) NSW

**Date:** 15 February 1986 **Time:** 1502

Highest Injury Level: Nil

**Injuries:** 

|           | Fatal | Serious | Minor | None |
|-----------|-------|---------|-------|------|
| Crew      | 0     | 0       | 1     | 1    |
| Ground    | 0     | 0       | 0     | -    |
| Passenger | 0     | 0       | 0     | 0    |
| Total     | 0     | 0       | 0     | 1    |

**Aircraft Details:** Grob Astir CS **Registration:** VH-WVM

**Serial Number:** 

Operation Type: Private (Gliding)
Damage Level: Substantial
Departure Point: Bunyan NSW

**Departure Time:** 1450

**Destination:** Bunyan NSW

**Approved for Release:** August 1st 1986

## **Circumstances:**

The pilot was making a landing approach and intended to touch down at the threshold of the strip. The strip had recently been mown and its edges were clearly defined, however it was surrounded by long grass. Touchdown occurred short of the threshold, the left wing entered the long grass and the glider ground looped. There was no operational reason for the pilot to attempt to land at the threshold of the strip. The grass surrounding the strip was higher than the pilot anticipated.