Aviation Safety Investigation Report 198602663

Grumman AA5-B

5 September 1986

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the CEO of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the CEO of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at www.atsb.gov.au.

Occurrence Number: 198602663 Occurrence Type: Accident

Location: Birdsville QLD

Date: 5 September 1986 **Time:** 1350

Highest Injury Level: Nil

Injuries:

	Fatal	Serious	Minor	None
Crew	0	0	1	1
Ground	0	0	0	-
Passenger	0	0	0	2
Total	0	0	0	3

Aircraft Details: Grumman AA5-B

Registration: VH-IFS

Serial Number:

Operation Type: Private-Travel
Damage Level: Substantial
Departure Point: Windorah QLD

Departure Time: 1155

Destination: Birdsville QLD

Approved for Release: November 13th 1986

Circumstances:

The pilot had held a Private Pilot Licence which had expired about six months prior to the accident. A witness reported that after the aircraft touched down it bounced about three times before landing in a nose down attitude which resulted in the nosegear strut failing in overload. The landing was attempted in a 10 knot crosswind and the pilot reported that the aircraft was affected by a wind gust during the landing sequence. The pilot was not in recent flying practice and had not flown for about five months prior to this trip.