

**Aviation Safety Investigation Report
198400024**

Cessna 182-Q

22 May 1984

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the CEO of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the CEO of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at www.atsb.gov.au.

Occurrence Number: 198400024**Occurrence Type:** Accident**Location:** Vergemont Station, 145 km W of Longreach QLD**Date:** 22 May 1984**Time:** 1640**Highest Injury Level:** Nil**Injuries:**

	Fatal	Serious	Minor	None
Crew	0	0	1	1
Ground	0	0	0	-
Passenger	0	0	0	0
Total	0	0	0	1

Aircraft Details: Cessna 182-Q**Registration:** VH-FRV**Serial Number:****Operation Type:** Cattle Spotting**Damage Level:** Substantial**Departure Point:** Vergemont Station QLD**Departure Time:** 1325**Destination:** Vergemont Station QLD**Approved for Release:** 25th September 1984**Circumstances:**

The pilot reported that his approach to land towards the north-west was good, however the aircraft floated for some distance before touching down. As the aircraft landed the sun appeared from behind a cloud and the pilot lost all forward vision. Braking was applied but, as the pilot considered that the aircraft was not slowing down and he was aware that the strip end was near, he applied power to go around. The aircraft failed to become airborne and collided with a bush and a fence beyond the end of the strip. The investigation did not reveal any fault with the aircraft that could have contributed to the accident.