Aviation Safety Investigation Report 198204544

Cessna 172RG

9 October 1982

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the CEO of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the CEO of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at www.atsb.gov.au.

Occurrence Number: 198204544 Occurrence Type: Accident

Location: Lake Grace WA

Date: 9 October 1982 **Time:** 2140

Highest Injury Level: Fatal

Injuries:

	Fatal	Serious	Minor	None
Crew	1	0	0	0
Ground	0	0	0	-
Passenger	2	0	0	0
Total	3	0	0	0

Aircraft Details: Cessna 172RG **Registration:** VH-WMX

Serial Number:

Operation Type: Non Commercial - Carriage

Damage Level: Destroyed
Departure Point: Lake Grace WA

Departure Time: 2140

Destination: Jandakot WA

Approved for Release: 28th February, 1984

Circumstances:

At the time of the accident, weather conditions were fine but it was a very dark night. The stars were obscured by a high overcast and there were only a few ground lights. The horizon was not visible. The take-off was into the southeast. Shortly after becoming airborne the aircraft entered a left turn and then began to descend. This continued until the aircraft struck the surface of a salt lake, in an inverted attitude. No contributory faults could be found with the aircraft or aircraft systems. The pilot was inexperienced in night operations and on this occasion there was a lack of external visual cues available. It is probable that the pilot became disorientated during the turn after take-off and lost control of the aircraft.