Aviation Safety Investigation Report 198602319

Cessna 172 M

09 March 1986

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the CEO of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the CEO of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at <u>www.atsb.gov.au</u>.

Occurrence Number: Location: Date: Highest Injury Level: Injuries:		Walcha NSW 09 March 1986			Occurrence Type: Accident Time: N/A	
J			Fatal	Serious	Minor	None
		Crew	0	0	1	1
		Ground	0	0	0	-
		Passenger	0	0	0	0
		Total	0	0	0	1
Aircraft Details:						
Registration: Serial Number:	ΥΠ-DΑ W					
	Aerial Work (Solo Training)					
Damage Level:	Substantial					
Departure Point:	Walcha NSW					
Departure Time:	N/A					
Destination:	Walcha NSW					

Approved for Release: April 14th 1986

Circumstances:

At the conclusion of a dual check flight, the student landed the aircraft into a light north-westerly wind. The landing roll was completed about half way along the 853 metre strip, and the pilot turned the aircraft around preparatory to taxying back to the upwind threshold. The instructor left the aircraft at this point, after briefing the student on the solo sequences he wished him to practice. Shortly afterwards, full power was applied as the student commenced a take-off downwind. The aircraft failed to become airborne, collided with a fence and overturned. The student was subsequently unable to give any reason for his decision to commence the take-off roll from other than the threshold of the strip.