Aviation Safety Investigation Report 198802339

Robinson R22

8 January 1988

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the CEO of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the CEO of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at www.atsb.gov.au.

Occurrence Number: 198802339 Occurrence Type: Accident

Location: Hoxton Park NSW

Time: 1440 Date: 8 January 1988

Highest Injury Level: Nil

Injuries:

	Fatal	Serious	Minor	None
Crew	0	0	2	2
Ground	0	0	0	-
Passenger	0	0	0	0
Total	0	0	0	2

Aircraft Details: Robinson R22

VH-CIU **Registration:**

Serial Number: 219

Aerial Work (Instructional

Operation Type: Dual)

Damage Level: Destroyed

Departure Point: Bankstown NSW

Departure Time: 1410

Destination: Hoxton Park NSW

Approved for Release: April 8th 1988

Circumstances:

The student was receiving instruction in autorotative techniques. The crew completed several autorotative descents terminating in power recoveries. The instructor then demonstrated an autorotation during initial climb at 50 knots, simulating an engine failure after take off. The helicopter was levelled and throttle and collective applied, but the instructor was unable to arrest the rate of descent and the helicopter landed heavily. Following a bounce, the left skid dug into the ground and the helicopter cartwheeled before coming to rest upright, facing in the reciprocal direction to the landing. The instructor commenced the practice autorotation after take off at too low a height/speed configuration. Despite the use of power, he was unable to reduce the excessive sink rate prior to ground impact.