

**Aviation Safety Investigation Report
198402356**

Cessna 182-A

17 December 1984

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the CEO of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the CEO of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at www.atsb.gov.au.

Occurrence Number: 198402356**Occurrence Type:** Accident**Location:** Interview River, 25 Km S of Sandy Cape, TAS**Date:** 17 December 1984**Time:** 1500**Highest Injury Level:** Nil**Injuries:**

	Fatal	Serious	Minor	None
Crew	0	0	1	1
Ground	0	0	0	-
Passenger	0	0	0	1
Total	0	0	0	2

Aircraft Details: Cessna 182-A**Registration:** VH-KLJ**Serial Number:****Operation Type:** Business Flight**Damage Level:** Substantial**Departure Point:** Sandy Cape TAS**Departure Time:** 1500**Destination:** Interview River TAS**Approved for Release:** 5th March, 1985**Circumstances:**

The pilot decided to land at the strip to check on the welfare of two mining company employees working in the area. During the latter stages of the landing roll the nosewheel entered a soft area and dug in, causing the aircraft to overturn. As the mining company's base radio was unserviceable and the ground personnel were not expecting the aircraft, the pilot was not able to establish the condition of the strip. Although it appeared serviceable from the air, the strip contained a section where water from recent rain had accumulated and resulted in the surface in that area being soft and wet.