

**Aviation Safety Investigation Report
198703502**

Cessna 172RG

13 September 1987

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the CEO of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the CEO of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at www.atsb.gov.au.

Occurrence Number: 198703502
Location: Toowoomba QLD
Date: 13 September 1987
Highest Injury Level: Nil
Injuries:

Occurrence Type: Accident

Time: 0915

	Fatal	Serious	Minor	None
Crew	0	0	1	1
Ground	0	0	0	-
Passenger	0	0	0	3
Total	0	0	0	4

Aircraft Details: Cessna 172RG
Registration: VH-KOS
Serial Number: 172RG0536
Operation Type: Private
Damage Level: Substantial
Departure Point: Archerfield QLD
Departure Time: 835
Destination: Toowoomba QLD

Approved for Release: September 24th 1987

Circumstances:

The pilot was manoeuvring the aircraft on the apron to park adjacent to another parked aircraft. Whilst making a right turn he was observing the other aircraft which was to his right, when the left wingtip struck a corner post of the airport boundary fence. The pilot had observed the fence post prior to commencing the turn and had assessed that there would be adequate clearance for the manoeuvre. However, he failed to continue monitoring the clearance with the post during the turn.