## 1

**Aviation Safety Investigation Report 197800035** 

**Hughes 269C** 

22 July 1978

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the CEO of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the CEO of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at www.atsb.gov.au.

Occurrence Number: 197800035 Occurrence Type: Accident

**Location:** 42km NE of Normanton QLD

**Date:** 22 July 1978 **Time:** 1110

**Highest Injury Level:** Serious

**Injuries:** 

	Fatal	Serious	Minor	None
Crew	0	1	0	0
Ground	0	0	0	-
Passenger	0	1	0	0
Total	0	2	0	0

**Aircraft Details:** Hughes 269C **Registration:** VH-THW

**Serial Number:** 

**Operation Type:** Aerial Work **Damage Level:** Destroyed

**Departure Point:** Delta Downs QLD

**Departure Time:** 955

**Destination:** Delta Downs QLD

**Approved for Release:** 12th December 1985

## **Circumstances:**

The helicopter was involved in cattle mustering operations. It was being flown at about 50 to 100 feet agl when a sudden yaw to the right developed. Attempts by the pilot to regain control of the aircraft were unsuccessful and it landed heavily while still rotating to the right. Both the occupants were thrown clear of the aircraft which caught fire immediately. The extensive fire damage to the aircraft inhibited the inspection of the wreckage. As a result, no reason for the apparent loss of control could be determined.