Aviation Safety Investigation Report 198201416

Cessna 182E

19 September 1982

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the CEO of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the CEO of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at <u>www.atsb.gov.au</u>.

Occurrence Nun Location: Date: Highest Injury L Injuries:	Corowa N 19 Septer	Corowa NSW 19 September 1982		Occurrence Type: Accident Time: 2035	
	Crew Ground Passenge	Fatal 0 1 r 0	Serious 0 0 0	Minor 1 0 0	None 1 - 1
	Total	1	0	0	2
Serial Number: Operation Type: T Damage Level: S Departure Point: C Departure Time: 2	YH-CDV Fravel ubstantial Corowa NSW				

Approved for Release: 3rd April, 1984

Circumstances:

The pilot was attempting to take-off at night from an unlit runway, using the headlights of a car positioned at the upwind threshold for guidance. After becoming airborne the aircraft failed to climb away normally and collided with the car, killing one of the occupants. Although the aircraft had sustained substantial damage it remained airborne, and a safe landing was carried out at the planned destination. It was calculated that the aircraft was travelling at an approximate airspeed of 105 kt when it struck the car. No fault was found with the aircraft that would have prevented it from climbing normally after lift off. The reason the aircraft failed to climb could not be determined.