

**Aviation Safety Investigation Report  
198601435**

**Cessna 172N**

**30 October 1986**

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the CEO of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the CEO of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

**NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at [www.atsb.gov.au](http://www.atsb.gov.au).**

**Occurrence Number:** 198601435**Occurrence Type:** Accident**Location:** Harewood (2.5 km SE Tooradin) VIC**Date:** 30 October 1986**Time:** 1345**Highest Injury Level:** Nil**Injuries:**

	Fatal	Serious	Minor	None
Crew	0	0	1	1
Ground	0	0	0	-
Passenger	0	0	0	0
<b>Total</b>	<b>0</b>	<b>0</b>	<b>0</b>	<b>1</b>

**Aircraft Details:** Cessna 172N**Registration:** VH-WSI**Serial Number:****Operation Type:** Aerial Work (Solo Training)**Damage Level:** Substantial**Departure Point:** Harewood VIC**Departure Time:** 1345**Destination:** Harewood VIC**Approved for Release:** May 12th 1987**Circumstances:**

The pilot had been conducting a series of solo circuits and landings. On the seventh circuit, a normal approach was flown but the aircraft ballooned slightly as the flare was commenced. The aircraft was then seen to climb abruptly to a height of about 20 feet, and shortly afterwards the left wing dropped. Full power was applied, but descent continued and the left wing tip struck the ground. The aircraft slewed rapidly to the left and the nose struck the side of a ditch. During his training, the pilot had experienced some inconsistency in the control of the landing flare. On this occasion he had evidently applied rearward pressure to the control column, and had not relaxed this pressure before the aircraft stalled.