Aviation Safety Investigation Report 198703520

Bell 206-B

24 November 1987

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the CEO of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the CEO of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at <u>www.atsb.gov.au</u>.

Occurrence Number: Location: Date: Highest Injury Level: Injuries:		12 km NW of Ravenshoe QLD 24 November 1987			Occurrence Type: Accident Time: 1358	
injuites.			Fatal	Serious	Minor	None
		Crew	0	0	1	1
		Ground	0	0	0	-
		Passenger	0	0	0	1
		Total	0	0	0	2
Aircraft Details:						
Registration:	VH-FJB					
Serial Number:	1458					
Operation Type:	Aerial Work (Mineral Exploration)					
Damage Level:	Substantial					
Departure Point:	Ravenshoe QLD					
Departure Time:	1230					
Destination:	Ravenshoe QLD					

Approved for Release: 14 June 1988

Circumstances:

The helicopter was engaged in the transport of personnel for stream sampling operations. The pilot was to collect one of the samplers from a sloping area which had recently had trees cut down to facilitate the approach. To achieve the pick up, the helicopter was manoeuvred so that the left skid was resting on a slab of rock, and the right skid remained in the air, about 120 millimetres from a tree stump. As the passenger approached the aircraft, the pilot adjusted the position of the skid on the rock and the right skid contacted the stump. The helicopter then rapidly rolled onto its side. This accident was not the subject of an on scene investigation.