

**Aviation Safety Investigation Report
198600132**

Piper PA31

3 March 1986

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the CEO of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the CEO of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at www.atsb.gov.au.

Occurrence Number: 198600132
Location: Derby WA
Date: 3 March 1986
Highest Injury Level: Nil
Injuries:

	Fatal	Serious	Minor	None
Crew	0	0	3	3
Ground	0	0	0	-
Passenger	0	0	0	0
Total	0	0	0	3

Aircraft Details: Piper PA31
Registration: VH-WDY
Serial Number:
Operation Type: Aerial Work-Ambulance
Damage Level: Substantial
Departure Point: Derby WA
Departure Time: 1940
Destination: Broome WA

Approved for Release: May 13th 1987

Circumstances:

The pilot commenced the take-off run and confirmed that full power was selected. At an indicated airspeed of 90 knots, he rotated the aircraft and waited for the performance instruments to indicate that a positive rate of climb and the single engine climb speed had been achieved. The pilot reported that the aircraft did not accelerate beyond an airspeed of 95 knots and a positive rate of climb was not obtained. He stated that he retracted the gear, to avoid having it snag the boundary fence, and then realised that the left engine was losing power and altitude was not being maintained. The pilot then closed the throttles and the aircraft landed in open country beyond the aerodrome boundary. An inspection of the aircraft did not detect any faults in the engines or other aircraft systems that could have contributed to the occurrence. An examination of the propellers indicated that both engines were delivering power at the time the aircraft struck the ground. The cause of this accident remains undetermined.