

**Aviation Safety Investigation Report
198602682**

Ikarus Fox

2 March 1986

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the CEO of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the CEO of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at www.atsb.gov.au.

Occurrence Number: 198602682
Location: Warwick QLD
Date: 2 March 1986
Highest Injury Level: Minor
Injuries:

Occurrence Type: Accident

Time: 0651

	Fatal	Serious	Minor	None
Crew	0	0	0	0
Ground	0	0	0	-
Passenger	0	0	0	0
Total	0	0	1	0

Aircraft Details: Ikarus Fox
Registration: Not registered
Serial Number:
Operation Type: Private-Pleasure
Damage Level: Substantial
Departure Point: Warwick QLD
Departure Time: 650
Destination: Warwick QLD

Approved for Release: September 4th 1986

Circumstances:

At about 300 feet on climb after take-off, the engine suffered a partial loss of power. The pilot turned the aircraft back towards the strip and shortly after aligning it for landing, the engine suffered a further loss of power. The pilot was unable to avoid power lines on the approach path and the aircraft collided with the wires before coming to rest near a house. The engine was still running when the aircraft struck the ground, and the reason for the decrease in performance could not be established.