Aviation Safety Investigation Report 198502507

Bell 206B

6 January 1985

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the CEO of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the CEO of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at <u>www.atsb.gov.au</u>.

Occurrence Number: Location: Date: Highest Injury Level: Injuries:		"Pasodoble", Hoskinstown (20 km 6 January 1985			Occurrence Type: Accident SE Canberra), NSW. Time: 1100	
-injui iosi			Fatal	Serious	Minor	None
		Crew	0	1	0	0
		Ground	0	0	0	-
		Passenger	0	1	1	0
		Total	0	2	1	0
Damage Level: Departure Point:	VH-BHC Bushfire Control Activities Destroyed "Pasodoble", NSW.					
Departure Time: Destination:	"Woolcara", NSW. (10 km S "Pasodoble")					

Approved for Release: 10th May, 1985

Circumstances:

Just after lift off, the pilot initiated a climbing left turn and the helicopter struck a powerline about 120 metres from the take-off point. Control of the helicopter was lost, it impacted the ground and rolled inverted. The occupants were able to evacuate the wreckage before it was destroyed by fire. The pilot was not aware of the existence of the powerline and did not see it during a pre-take off check of the DEPARTURE path. The nearest support pole indicating the existence of the powerline was surrounded by trees and the mottled background afforded a poor contrast for the detection of the wires.