Aviation Safety Investigation Report 198903822

Robinson

21 November 1989

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the CEO of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the CEO of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at <u>www.atsb.gov.au</u>.

		Occurrence Type: Accident of Boulia) OLD		
		Time: 1050		
			-	
	Fatal	Serious	Minor	None
Crew	0	0	1	1
Ground	0	0	0	-
Passenger	0	0	0	0
Total	0	0	0	1
on				
Registration: VH-JZH				
ntial				
Departure Point: Pollygammon Station QLD				
	Pollygamn 21 Novem Nil Crew Ground Passenger Total on H	21 November 1989 Nil Fatal Crew 0 Ground 0 Passenger 0 Total 0 on H	Pollygammon Station (40km NE of 21 November 1989 Nil Fatal Serious Crew 0 0 Ground 0 0 Passenger 0 0 Total 0 0 on H	Pollygammon Station (40km NE of Boulia) Q 21 November 1989 Time: 105 Nil Fatal Serious Minor Crew 0 0 1 Ground 0 0 0 Passenger 0 0 0 Total 0 0 0 on H

This accident was not formally investigated by the Bureau.

Pollygammon Station QLD

Approved for Release: 12 March 1990

Circumstances:

Destination:

The pilot had been engaged in sheep spotting for a period of approximately three hours, and was returning to the refuelling pad. Enroute he observed a motorcycle stockman, and landed the aircraft in a cleared area nearby, to advise him of the location of a mob of sheep he had spotted earlier. The pilot advised that after he had landed he left the engine running at between 70 and 80 percent rotor/engine speed