

**Aviation Safety Investigation Report  
198602679**

**Piper PA18-125-A1**

**22 December 1986**

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the CEO of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the CEO of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

**NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at [www.atsb.gov.au](http://www.atsb.gov.au).**

**Occurrence Number:** 198602679  
**Location:** Redcliffe QLD  
**Date:** 22 December 1986  
**Highest Injury Level:** Nil  
**Injuries:**

	Fatal	Serious	Minor	None
Crew	0	0	2	2
Ground	0	0	0	-
Passenger	0	0	0	0
<b>Total</b>	<b>0</b>	<b>0</b>	<b>0</b>	<b>2</b>

**Aircraft Details:** Piper PA18-125-A1  
**Registration:** VH-HCM  
**Serial Number:**  
**Operation Type:** Aerial Work-Dual instruction  
**Damage Level:** Substantial  
**Departure Point:** Redcliffe QLD  
**Departure Time:** N/A  
**Destination:** Redcliffe QLD

**Approved for Release:** May 4th 1987

**Circumstances:**

The student had completed about seven hours training and was undergoing her second session of circuit training. The instructor stated that the student had previously had difficulty with the directional control of the aircraft. On this takeoff he allowed the student to manipulate only the rudder, so that she could concentrate on the directional control aspect, while he manipulated all the other controls. As the power was increased the aircraft gradually swung to the left. Approaching the left side of the strip the swing increased and the instructor applied right rudder at the same time as the student. The aircraft swung to the right and as it crossed the right side of the strip the left wheel dug into the ground and the aircraft tipped onto the left wing.