## **Aviation Safety Investigation Report 198703503**

Beech A36 Bonanza

14 September 1987

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the CEO of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the CEO of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at <a href="https://www.atsb.gov.au">www.atsb.gov.au</a>.

Occurrence Number: 198703503 Occurrence Type: Accident

**Location:** Willow Glen 76 km WNW Goondiwindi QLD **Date:** 14 September 1987 **Time:** 935

Highest Injury Level: Nil

**Injuries:** 

	Fatal	Serious	Minor	None
Crew	0	0	1	1
Ground	0	0	0	-
Passenger	0	0	0	3
Total	0	0	0	4

Aircraft Details: Beech A36 Bonanza

Registration: VH-TLB
Serial Number: E-533
Operation Type: Private
Damage Level: Substantial
Departure Point: Gunnedah NSW

**Departure Time:** 0819

**Destination:** Willow Glen QLD

Approved for Release: November 4th 1987

## **Circumstances:**

The pilot had landed at the strip on a number of previous occasions, but this was the first time in this aircraft type. To give himself more time the pilot made a longer than normal final approach. At about 100 feet above the ground, with the airspeed at about 65 knots, the aircraft began to sink. The pilot applied full power to commence a go-around and as the nose pitched up, the left wing dropped. The pilot did not prevent the nose of the aircraft pitching up, thus aggravating the almost stalled condition of the aircraft. Power was then reduced and the aircraft landed heavily in a wheat paddock along side the strip and slid sideways as it came to rest.