Aviation Safety Investigation Report 199003048

Cessna A188B-A1

30 January 1990

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the CEO of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the CEO of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at <u>www.atsb.gov.au</u>.

This accident was not formally investigated by the Bureau.					
Occurrence Number: 199003048		3		Occurrence Type: Accident	
Location:	6 km West	6 km West of Thangool QLD			
Date:	30 January	30 January 1990		Time: 1820	
Highest Injury Level	l: Nil	Nil			
Injuries:					
		Fatal	Serious	Minor	None
	Crew	0	0	1	1
	Ground	0	0	0	-
	Passenger	0	0	0	0
	Total	0	0	0	1
Aircraft Details: Cessna A188B-A1					
Registration: VH-I	VH-IEZ				
Serial Number: N/K	N/K				
Operation Type: Aeria	Aerial Work				
Damage Level: Destru	Destroyed				
Departure Point: Biloela QLD					

This accident was not formally investigated by the Bureau

Approved for Release: 13th December 1990

Biloela QLD

Circumstances:

Destination:

Departure Time: N/K

The pilot reported that he was spraying a crop with the runs oriented in a racetrack pattern across the wind, which was south-easterly at 15 knots. This resulted in a turn into wind at one end and a turn downwind at the other end. He experienced difficulty in preventing the aircraft drifting away from the paddock during the downwind turns and was widening the turns in an attempt to correct the problem. During the third downwind turn the aircraft stalled but the pilot was unable to level the wings due to trees in the path of the aircraft. The right wing struck a fence and cartwheeled into a paddock.