## **Aviation Safety Investigation Report 198400023**

Partenavia P68B

16 May 1984

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the CEO of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the CEO of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at www.atsb.gov.au.

Occurrence Number: 198400023 Occurrence Type: Accident

**Location:** Horn Island QLD

**Date:** 16 May 1984 **Time:** 1500

Highest Injury Level: Nil

**Injuries:** 

	Fatal	Serious	Minor	None
Crew	0	0	1	1
Ground	0	0	0	-
Passenger	0	0	0	4
Total	0	0	0	5

Aircraft Details: Partenavia P68B

**Registration:** VH-FAO

**Serial Number:** 41 **Operation Type:** Charter **Damage Level:** Substantial

**Departure Point:** Murray Island QLD

**Departure Time:** 1351

**Destination:** Horn Island QLD

**Approved for Release:** 16 May 1984

## **Circumstances:**

Severe turbulence had been encountered on final approach but smooth air was entered on short final. After flaring to land, the aircraft rolled left rapidly and the landing was made on the left main wheel, followed by the right and nose wheels. The pilot subsequently inspected the aircraft but did not detect any damage. After two further flights the pilot noticed that the left wing appeared to be low. Distortion of the left main gear support frame was found.