1

Aviation Safety Investigation Report 198502565

Piper PA 36-375

18 November 1985

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the CEO of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the CEO of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at www.atsb.gov.au.

Occurrence Number: 198502565 Occurrence Type: Accident

Location: Benerembah, 26 km SW Griffith NSW

Date: 18 November 1985 **Time:** 1145

Highest Injury Level: Minor

Injuries:

	Fatal	Serious	Minor	None
Crew	0	0	0	0
Ground	0	0	0	-
Passenger	0	0	0	0
Total	0	0	1	0

Aircraft Details: Piper PA 36-375

Registration: VH-JND

Serial Number:

Aerial Work (Agricultural

Operation Type: Actial Work Spraying)

Damage Level: Substantial

Departure Point: Griffith NSW

Departure Time: 1145

Destination: Griffith NSW

Approved for Release: 30th January, 1986

Circumstances:

The pilot was carrying out the first spraying run in the particular paddock. Towards the end of the run he was distracted when a large flock of birds suddenly flew up in front of the aircraft. The pilot descended in order to fly under the birds, but temporarily forgot that there was a power line in the vicinity. As he pulled up at the end of the run, the main gear snagged the wire. The wire cutters fitted to the gear did not sever the wire and the aircraft subsequently struck the ground 82 metres beyond the run of the power line.