## 1

**Aviation Safety Investigation Report 198401403** 

Piper PA38-112

4 September 1984

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the CEO of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the CEO of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at www.atsb.gov.au.

Occurrence Number: 198401403 Occurrence Type: Accident

**Location:** Bankstown NSW

**Date:** 4 September 1984 **Time:** 1037

**Highest Injury Level:** Nil

**Injuries:** 

	Fatal	Serious	Minor	None
Crew	0	0	1	1
Ground	0	0	0	-
Passenger	0	0	0	0
Total	0	0	0	1

**Aircraft Details:** Piper PA38-112 **Registration:** VH-HAV

**Serial Number:** 

**Operation Type:** Instructional Solo

Damage Level: Substantial

**Departure Point:** Bankstown NSW

**Departure Time:** 1033

**Destination:** Bankstown NSW

**Approved for Release:** 11th April 1985

## **Circumstances:**

Following a period of dual instruction the pilot was authorised to carry out her second solo circuit and landing. During the landing flare the aircraft ballooned and subsequently touched down on the nosewheel. The aircraft bounced and on the next touchdown the nosewheel broke off, the nose gear leg was displaced and the aircraft slid to a halt on the runway. The pilot's previous training flight had been conducted approximately one month prior to the accident. After misjudging the landing flare, the pilot persisted with the landing attempt instead of going around.