**Aviation Safety Investigation Report 198400058** 

**Piper PA28-151** 

**26 December 1984** 

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the CEO of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the CEO of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at www.atsb.gov.au.

Occurrence Number: 198400058 Occurrence Type: Accident

**Location:** Glenaubyn', 32 Km NW of Miles QLD

**Date:** 26 December 1984 **Time:** 1335

**Highest Injury Level:** Nil

**Injuries:** 

	Fatal	Serious	Minor	None
Crew	0	0	1	1
Ground	0	0	0	-
Passenger	0	0	0	3
Total	0	0	0	4

Aircraft Details: Piper PA28-151

**Registration:** VH-PZC

**Serial Number:** 

**Operation Type:** Pleasure Flight **Damage Level:** Substantial **Departure Point:** Glenaubyn' QLD

**Departure Time:** N/A

**Destination:** Capella QLD

**Approved for Release:** 5th March 1985

## **Circumstances:**

The pilot intended landing in a paddock to inspect the results of recent spraying. He was aware of a power line well beyond the intended landing area. Sheep obstructed all of the paddock but the pilot hesitated in going round. Having temporarily forgotten about the power line, he then saw it too late to climb over and the top of the fin was severed as the aircraft was flown under the wire. The impact jammed the rudder, however the pilot was able to carry out a safe landing in the adjoining paddock.