Aviation Safety Investigation Report 199900461

Embraer-Empresa Brasileira de Aeronautica Piper Chieftain

10 February 1999

Aviation Safety Investigation Report 199900461

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at www.atsb.gov.au.

199900461

Occurrence Number: 199900461 Occurrence Type: Accident

Location: Coonabarabran, Aerodrome

State: NSW Inv Category: 4

Date: Wednesday 10 February 1999

Time: 0545 hours **Time Zone** ESuT

Highest Injury Level: None

Aircraft Embraer-Empresa Brasileira de Aeronautica

Manufacturer:

Aircraft Model: EMB-820-C

Aircraft Registration: VH-HVA Serial 820C-045

Number:

Type of Operation: Air Transport Domestic Low Capacity Passenger

Positioning

Damage to Aircraft: Substantial

Departure Point: Coonabarabran NSW

Departure Time: 0545 ESuT

Destination: Gunnedah NSW

Crew Details:

Role Hours on Type Hours Total

Pilot-In-Command ATPL 350.0 3160

Approved for Release: Friday, July 9, 1999

During the takeoff run, the aircraft's nose landing gear collided with a pig that had strayed onto the runway. The nose landing gear collapsed, causing both propellers to strike the ground.

The aerodrome was surrounded by an electric fence designed to prevent the entry of animals. This had been breached once before, and the fence had been repaired. An inspection by the council aerodrome inspector did not reveal where the pig had gained entry.

The inspector now conducts daily inspections of the aerodrome area before the arrival of the regular public transport flight, and the electric fence power unit has been upgraded.