Aviation Safety Investigation Report 199800752

Cessna Aircraft Company Skyhawk

20 February 1998

Aviation Safety Investigation Report 199800752

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at www.atsb.gov.au.

Aviation Safety Investigation Report

199800752

Occurrence Number: 199800752 Occurrence Type: Accident

Location: Bruny Island, (ALA)

Inv Category: State: TAS

Friday 20 February 1998 Date:

Time: 1840 hours Time Zone **ESuT**

Highest Injury Level: None

Aircraft Manufacturer: Cessna Aircraft Company

Aircraft Model: 172P

Aircraft Registration: VH-SIZ Serial Number: 17274689

Type of Operation: Non-commercial Pleasure/Travel

Damage to Aircraft: Substantial **Departure Point:** Cambridge Tas. **Departure Time:** 1740 ESuT

Destination: Bruny Island Tas.

Crew Details:

Hours on **Type Hours Total** Role **Class of Licence** Pilot-In-Command Private 69.5

Approved for Release: Monday, July 6, 1998

While landing towards the north-west at Bruny Island, the aircraft landed heavily and bounced, tearing the nose landing gear from the aircraft and bending the propeller. The pilot and three passengers evacuated the aircraft without injury. The pilot reported that he suspected wind shear may have been a factor.