Aviation Safety Investigation Report 199801179

Cessna Aircraft Company 182C

14 March 1998

Aviation Safety Investigation Report 199801179

Readers are advised that the Australian Transport Safety Bureau investigates for the sole purpose of enhancing transport safety. Consequently, Bureau reports are confined to matters of safety significance and may be misleading if used for any other purposes.

Investigations commenced on or before 30 June 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with Part 2A of the Air Navigation Act 1920.

Investigations commenced after 1 July 2003, including the publication of reports as a result of those investigations, are authorised by the Executive Director of the Bureau in accordance with the Transport Safety Investigation Act 2003 (TSI Act). Reports released under the TSI Act are not admissible as evidence in any civil or criminal proceedings.

NOTE: All air safety occurrences reported to the ATSB are categorised and recorded. For a detailed explanation on Category definitions please refer to the ATSB website at www.atsb.gov.au.

Aviation Safety Investigation Report

199801179

Occurrence Number: 199801179 Occurrence Type: Accident

Location: 2km E Goulburn

State: NSW Inv Category: 4

Date: Saturday 14 March 1998

Time: 1336 hours **Time Zone** ESuT

Highest Injury Level: None

Aircraft Manufacturer: Cessna Aircraft Company

Aircraft Model: 182C

Aircraft Registration: VH-DBX Serial Number: 52482

Type of Operation: Miscellaneous Parachute Jump

Damage to Aircraft:SubstantialDeparture Point:Goulburn NSWDeparture Time:1300 ESuTDestination:Goulburn NSW

Crew Details:

Hours on

Role	Class of Licence	Type Hou	ırs Total
Pilot-In-Command	Commercial	41.7	650

Approved for Release: Monday, May 25, 1998

On descent through 8,000 feet, the engine of VH-DBX started running rough. The pilot carried out the emergency check list procedures and found no response to throttle so he shut the engine down. Melbourne Flight Service (FS) was then informed by the pilot of his intention to land short of Goulburn. Another aircraft in the vicinity, VH-RPO, was diverted by FS to render assistance. The pilot of DBX did not declare an emergency, however FS initiate a Distress Phase. On short final to the selected landing site at approximately 20 feet AGL, the aircraft contacted a power line, rolled to the left and impacted the ground in a nose down attitude. The aircraft was then vacated with nil injuries. The pilot of RPO informed FS that an ambulance was in attendance and the Distress Phase was cancelled.

A report has been requested for the engine strip and inspection.